

From: Aaron R. Phillips <aphillips@asphaltroofing.org>
Sent: Wednesday, January 7, 2026 2:18 PM
To: Madani, Mo <Mo.Madani@myfloridalicense.com>
Subject: Florida Supplements - Issues Requiring Attention

[NOTICE] This message comes from a system outside of DBPR. Please exercise caution when clicking on links and/or providing sensitive information. If you have concerns, please contact your Knowledge Champion or the DBPR Helpdesk.

Hello Mo,

My review of the supplements identifies the following which require review and correction:

FBC, Building

- F11032
 - It appears that the language included in Section 1015.2 of the supplement is from the original ICC proposal (i.e., G106-21 Part II) instead of from Public Comment 1, which is what was approved in the IBC.

FBC, Residential

- R11576. The title of Table R905.6.8 contains a misspelling of the word “Accordacne”. This was misspelled in the original ICC proposal RB268-22.
- R11583. The number of the table in the table title is incorrect. It should be “R905.18.2” not “R905.182”.

FBC, Building – Referenced Standards

- R11849.
 - Should read “D4897/D4897M-16(2023)”. There should not be an “a” after “16.”
 - Should read “D6509/D6509M-16(2023)”. The “16” is missing.
 - Should read “F1667/F1667M-21a”. Missing “/F1667M”.
 - Should read “4470 (April 2022)”. The “2016” should be stricken.

FBC, Residential – Referenced Standards

- R11902.
 - Should read “C728-2017a(2022)”. The “A” should be lowercase.
 - Should read “D41/D41M-11(2023)”. The “11” is missing.
 - Should read “D226/D226M-17(2023)”. Remove “2017” and replace with “17”.
 - Should read “D312/D312M-16a(2023)”. Remove “2016” and replace with “16”.
 - Should read “D1863/D1863M-05(2024)”. Remove “2005” and replace with “05”.
 - Should read “D2824/D2824M-18(2024)”. Remove “2018” and replace with “18”.
 - Should read “D3019/D3019M-17(2024)”. Remove “2017” and replace with “17”.
 - Should read “D4479/D4479M-07(2024)”. The first “D4479” is missing. Also, remove “2007” and replace with “07”.
 - Should read “D4586/D4586M-07(2024)”. Remove “2007” and replace with “07”.
 - Should read “D4897/D4897M-16(2023)”. Remove “2016” and replace with “16”.

- Should read “D6222/D6222M-16(2023)”. Remove “2016” and replace with “16”.
- Should read “D6298/D6298M-16(2023)”. Remove “2016” and replace with “16”.
- Should read “D6757/D6757M-18(2023)”. Remove “2018” and replace with “18”.
- Should read “F1667/F1667M-21a”. Add “/F1667”.

FBC, Energy Conservation – Referenced Standards

- EN11905 (Commercial)
 - Should read “C1371-15(2022)”.
 - Should read “C1549-16(2022)”.
 - Should read “E84-24”.
 - Should read “E903-20”.
 - Should read “E1980-24”.
 - Should read “ANSI/CRRC S100-2025”.
- EN11906 (Residential)
 - Should read “C578-23”.
 - Should read “C1289-23a”.
 - Should read “C1371-15(2022)”.
 - Should read “C1549-16(2022)”.
 - Should read “ANSI/CRRC S100-2025 Standard Test Methods for Determining Radiative Properties of Materials”.
- EN12155 (Commercial)
 - Should read “ANSI/CRRC S100-2025 Standard Test Methods for Determining Radiative Properties of Materials”.
 - Cool Roof Rating Council address should be updated to “8797 N Lombard Street, Portland, OR 97203”.
- EN12151 (Residential)
 - Should read “ANSI/CRRC S100-2025”
 - Cool Roof Rating Council address should be updated to “8797 N Lombard Street, Portland, OR 97203”.
 - Add to index section “C402.3.1”.

Let me know if you have any questions or need anything else from me.

Take care,

Aaron



Aaron R. Phillips | Vice President of Technical Services

Asphalt Roofing Manufacturers Association (ARMA) 
 (620) 202-0922 | aphillips@asphaltroofing.org