






SECTION A
SCALE: 1/2 FULL
(FRAME SCREW MOUNT CONDITION SHOWN, FOR CLIP MOUNT CONDITIONS, SEE OPTIONAL CLIP MOUNT DETAILS)
NOTE: FRAME SCREWS ARE NOT REQUIRED AT SILL



SECTION B
SCALE: 1/2 FULL
(FRAME SCREW MOUNT CONDITION SHOWN, FOR CLIP MOUNT CONDITIONS, SEE OPTIONAL CLIP MOUNT DETAILS)



OPTIONAL INSTALLATION CLIP DETAIL 1
(SIDE SECTION SHOWN, HEAD IS INSTALLED THE SAME)
NOTE: INSTALLATION CLIPS NOT REQUIRED AT SILL



OPTIONAL INSTALLATION CLIP DETAIL 2
(SIDE SECTION SHOWN, HEAD IS INSTALLED THE SAME)
NOTE: INSTALLATION CLIPS NOT REQUIRED AT SILL

DRAWN BY: S.T.R.		CHECKED BY: W.W.S.	
PLOT: 1=2		DATE: 1/13/05	
NO.	REVISION DESCRIPTION	DATE	BY
DRAWING TITLE: PINNACLE ALUMINUM CLAD WOOD IMPACT DOUBLE HUNG PICTURE WINDOW			
MANUFACTURER: WINDSOR WINDOWS & DOORS 900 S. 19TH STREET WEST DES MOINES, IA 50265 800-218-6186			
CONSULTANTS: W. W. SCHAEFER ENGINEERING & CONSULTING, P.A. 8885 N. MILITARY TRAIL, SUITE C-204 PALM BEACH GARDENS, FL 33410 PHONE: 561-775-4902 FAX: 561-775-4903			
CERTIFICATION: APR 07 2009 WARREN W. SCHAEFER, P.E. P.E. NO. 44135			
DRAWING NO. 1371		REV. B	
SHEET NO. 2 OF 2			