



August 12, 2017

Florida Department of Business and Professional Regulation
1940 North Monroe Street, Tallahassee FL 32399


Regarding: Structall Building Systems, Inc.
EPS Foam Core Roof Panels – Metal Skin
15-2409a

To Whom It May Concern:

This office has reviewed test reports showing structural performance of the above-noted product. These test reports pertain to testing performed in accordance with ASTM E72-98 & ASTM E72-05 Standard Test Methods of Conducting Strength Tests of Panels for Building Construction. These standards have not been adopted in the Florida Building Code Sixth Edition (2017), but serves as an applicable test method in accordance with sections 104.11.2 & 1708.3 for the purpose of determining structural performance of this product.

This office has also reviewed test reports showing burn characteristics of the above-noted product. These test reports pertain to testing performed in accordance with ASTM E84-91 Test Method for Surface Burning Characteristics of Building Materials. This standard is not adopted in the Florida Building Code Sixth Edition (2017), but this Test method is equivalent to ASTM E84-13A which is adopted in the Florida Building Code Sixth Edition (2017).

Respectfully,



Frank L. Bennardo, P.E.
ENGINEERING EXPRESS®
#PE0046549 | Cert. Auth. 9885

15-2409