

Mo & Betty,

I have been looking at the 1/28 workgroup comments and proposals here are some of my comments:

101.2 covering this language should be the same as in 101.1

201.2 (E) I do not understand the reasoning for this option. This option if used would allow water to set in the joints of the plywood if water were to breach the primary roof covering and could cause plywood blistering or delaminating. This could cause a life safety issue when reroofing. SWB should be done from the top side of the deck. Most residential roofing systems require an underlayment if the underlayment is fastened accordingly it will meet the SWB requirements.

201.3 holes shall be deemed . verbiage should be added that such repairs must span 3 trusses edge to edge with one in the center

Billy Cone

President of the Florida Roofing, Sheet Metal & Air Conditioning Contractors
Association

RoofTech Roofing & Sheet Metal
3601 NW 10th Ave
Fort Lauderdale, FL. 33309
954-735-0807
954-735-0890 Fax