

Bluewater Maritime 3787 Old Middleburg Rd Jacksonville FL

| Description                     | Budget 10/23/23 |
|---------------------------------|-----------------|
|                                 |                 |
| Demo                            | \$9,005         |
| Concrete                        | \$9,500         |
| Masonry                         | \$4,377         |
| Wood Blocking                   | \$9,278         |
| Steel                           | \$4,800         |
| Millwork - Wood Trim / Cabinets | By owner        |
| Water proofing                  | \$410           |
| Doors & Hardware                | \$7,900         |
| Drywall / Ceiling               | \$12,495        |
| Exterior skin                   | \$2,100         |
| Specialties                     | \$310           |
| Painting                        | \$3,560         |
| Painting                        | \$1,025         |
| Electrical                      | \$800           |
|                                 |                 |
| Subtotal                        | \$65,560        |
| Building Permit                 | By owner        |
| Insurance Requirements          | \$1,210         |
| Builders Risk Insurance         | By owner        |
| General Conditions              | \$18,000        |
| P & P Bond                      | \$0             |
| Contingency                     | \$2,543         |
| Fee                             | \$10,478        |
|                                 |                 |
| Grand Total                     | \$97,790        |

## 97,790



Project: Bluewater Maritime 3787 Old Middleburg Rd Jacksonville FL

Location: Jacksonville, Florida
Date: October 23, 2023

1,255 NSF

GSF 7% added MATERIAL 43% added SUMMARY SHEET UNIT QTY UNIT COST COST CODE COST Div. 1 LS Demo Exterior 6,405.00 6,405 6,405 LS 2,600.00 2,600 2,600 Demo interior Division Summary - Site Requirement 9,005 DIV. 2 SITE SITEWORK Reworking some parking spots 0.00 Subtota 0.015 Div. 2 LANDSCAPE & IRRIGATION 0.00 Landscape / Irrigation Subtota 0.000 Bond rate Division Summary - LANDSCAPING 0 0.00 Div. 2 Hardscape Allowance Subtotal Bond rate 0.01 SF Div. 2 Deep Foundation Div. 3 TERMITE Termite Pretreatment LS 0.00 Subtota Bond rate 0.000 Div. 3 CONCRETE 1,500.00 3,000 Back room concrete leveling pour back/Pest control Subtota ,500 0.00 9,500 Bond rat 9,500 Div. 4 MASONRY 3,157.00 3,157 Repair and patch areas at stair landing 610.00 1,220 1,220 Subtotal 0.000 4,377 Division Summary - MASONRY 4,377 0.97 Div. 5 STEEL ls 2,400.00 4,800 4,800 Exterior Stairs/Railing 0.000 Division Summary - STEEL 4,800 1.07 Div. 6 ROUGH CARPENTRY Framing interior walls 150 55.00 8,828 3.00 450 9,278 sf sf 0.95 1.50 Misc. Wood Blocking 0.35 Subtota ,278 0.000 9,278 Bond rat Div. 6 FINISH CARPENTRY Subtotal Bond rate 0.000

| 1       |  | GSF                                   |       |      | added         |      | added            | aupaa                       | NED ACT               | TOTAL                                   | 10,00,00,47,00 |
|---------|--|---------------------------------------|-------|------|---------------|------|------------------|-----------------------------|-----------------------|---|----------------|
| CODE    | SUMMARY SHEET 97,790   | UNIT                                  | QTY   | UNIT | BOR<br>COST   | UNIT | IATERIAL<br>COST | UNIT                        | NTRACT<br>COST        | TOTAL<br>COST                           | 10/23/23 17:22 |
| Div. 7  | ROOFING  |                                       |       |      |               |      |                  |                             |                       |   |                |
| 2       |  | 0.5                                   |       |      |               |      |                  | 20.00                       |                       |   | NI             |
|         | Roofing 2ply built up<br>Walkway pads  | SF<br>Is                              | 0     |      | 0             |      | 0                | 30.00                       | 0                     | 0                                       | 1              |
|         | 20-year no dollar limit manufacturer's warranty 2-year contractor's labor warranty | ls<br>Is                              |       |      | 0             |      | 0                |                             | 0                     | 0                                       | 1              |
|         | Subtotal   | ls                                    |       |      |               |      |                  |                             |                       |   | 0              |
|         | Bond rate  | 10                                    | 0.000 |      |               |      |                  | 0                           | 0                     | 0                                       |                |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
| Div. 7  | WATERPROOFING  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         | Exterior doors on 2nd floor exterior wall Subtotal                                 | ls                                    | 2.000 |      |               |      |                  | 205                         | 410                   | 410                                     | 410            |
|         | Subtotal<br>Bond rate  | is                                    | 0.000 |      |               |      |                  | 410                         | 0                     | 0                                       |                |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         |  |                                       |       |      |               |      | Div              | ision Summary - THERMAL M   | DISTURE PROTECTION    | 410                                     | 0.09           |
|         |  |                                       |       |      |               |      | BIV              | ision outlinary Therawae IV | SIGNOTE THO TECHNICA  | 410                                     | 0.03           |
| Div. 8  | DOOR/FRAME/HARDWARE  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         | Exterior Doors: 2nd floor Stairs doors/w hardware and closure. M & L               | ea.                                   | 2     |      | 0             |      |                  | 2,150.00                    | 4,300                 | 4,300                                   |                |
|         |  |                                       |       |      |               |      |                  | ,                           | , , , ,               | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |                |
|         | Interior prehung   | unit                                  | 6     |      | 0             |      | 0                | 600.00                      | 3,600                 | 3,600                                   |                |
|         |  | unit                                  | 0     |      | 0             |      | 0                | 0.00                        | 0                     | 0                                       |                |
|         | Subtotal   | lo.                                   |       |      |               |      |                  |                             |                       |   | 7,900          |
|         | Subtotal<br>Bond rate  | ls                                    | 0.000 |      |               |      |                  | 7,900                       | 0                     | 0                                       |                |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         |  |                                       |       |      | _ <del></del> |      | <del></del>      | Division Summary -          | DOORS & HARDWARE      | 7,900                                   | 1.76           |
| Div. 8  | GLASS & GLAZING  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         | New Windows  | EA                                    | 0     |      | 0             |      | 0                | 0.00                        | 0                     | 0                                       |                |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         | Vanity Mirrors   | EA                                    | 0     |      | 0             |      | 0                | 0.00                        | 0                     | 0                                       |                |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         | Subtotal   | ls                                    |       |      |               |      |                  |                             |                       |   | 0              |
|         | Bond rate  |                                       | 0.000 |      |               |      |                  | 0                           | 0                     | 0                                       |                |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         |  | l                                     |       |      |               |      |                  | Division Summa              | ary - GLASS & GLAZING | 0                                       | 0.00           |
| Div. 9  | Exterior skin repair   | LS                                    | 300   |      | 0             |      | 0                | 7.00                        | 2,100                 | 2,100                                   |                |
|         |  |                                       | 300   |      | 0             |      |                  | 7.00                        | 2,100                 | 2,100                                   |                |
|         | Subtotal<br>Bond rate  | ls                                    | 0.000 |      |               |      |                  | 2,100                       | 0                     | 0                                       | 2,100          |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         |  | · · · · · · · · · · · · · · · · · · · |       |      | 1             |      | I                | Divis                       | ion Summary - STUCCO  | 2,100                                   | 0.47           |
| Div. 9  | DRYWALL / FRAMING / ACOUTSICAL CEILINGS  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         | ACT  | LS                                    | 425   |      | 0             |      |                  | 7.00                        | 2,975                 | 2,975                                   |                |
|         | Interior Fire Walls  | LF                                    | 80    |      | 0             |      | 0                | 119.00                      | 9,520                 | 9,520                                   |                |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         | Subtotal<br>Bond rate  | ls                                    | 0.000 |      |               |      |                  | 12,495                      | 0                     | 0                                       | 12,495         |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         |  | ·                                     |       |      | 1             |      | 1                | Divisio                     | n Summary - DRYWALL   | 12,495                                  | 2.78           |
| Div. 9  | FLOORING   | sf                                    | 0     |      | 0             |      | 0                | 30.00                       | 0                     | 0                                       |                |
|         | Minnor Floor prep  | SF                                    | 0     |      | 0             |      | 0                | 3.00                        | 0                     | 0                                       |                |
|         | Bathroom   | SF                                    | 0     |      | 0             |      | 0                | 10.00                       | 0                     | 0                                       |                |
|         | Bathroom tile base   | SF                                    | 0     |      | 0             |      | 0                | 6.00                        | 0                     | 0                                       |                |
|         | Subtotal   | ls                                    |       |      |               |      |                  |                             |                       |   | 0              |
|         | Bond rate  |                                       | 0.000 |      |               |      |                  | 0                           | 0                     | 0                                       |                |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
|         |  | <u> </u>                              |       |      |               |      | l                | Divisio                     | n Summary - FLOORING  | 0                                       | 0.00           |
| Div. 9  | PAINTING   |                                       |       |      |               |      |                  |                             |                       |   |                |
| 211. 3  |  | ļ ,                                   |       |      |               |      |                  |                             |                       |   |                |
|         | Painting Bid Interior wall affected areas  | Is                                    | 890   |      | 0             |      | 0                | 4.00                        | 3,560                 | 3,560                                   |                |
|         | Subtotal Bond rate   | ls                                    | 0.000 |      |               |      |                  | 3,560                       | 0                     | 0                                       | 3,560          |
|         | Solid falls  |                                       | 2.300 |      |               |      |                  | 2,300                       |                       |   |                |
|         |  |                                       |       |      | <u> </u>      |      | <u> </u>         | Divisi                      | on Summary - PAINTING | 3,560                                   | 0.79           |
|         |  |                                       |       |      |               |      |                  |                             |                       |   |                |
| Div. 42 | COMMERCIAL SPECIALTIES (non-units)   |                                       |       |      |               |      |                  |                             |                       |   |                |
| Div. 10 |  |                                       |       |      |               |      |                  | 4,493                       |                       |   |                |
|         | Paper Towel Unit<br>Grab bars  | EA<br>ea.                             | 0     |      | 0             |      | 0                | 75.00<br>85.00              | 0                     | 0                                       |                |
|         | Toilet Tissue Dispenser  | ea.                                   | 0     |      | 0             |      | 0                | 55.00                       | 0                     | 0                                       |                |
|         | Soap Dispenser<br>Interior signage   | ea.<br>Is                             | 0     |      | 0             |      | 0                | 35.00<br>500.00             | 0                     | 0                                       |                |
|         | Fire Extinguishers & Cabinets (public areas) Fire Extinguishers (private units)    | ea.                                   | 0 2   |      | 0             |      | 0                | 250.00<br>155.00            | 0<br>310              | 0<br>310                                |                |
|         | Subtotal   | ls                                    |       |      |               |      |                  |                             |                       |   | 310            |
|         | Subtotal<br>Bond rate  | ıs                                    | 0.000 |      |               |      |                  | 310                         | 0                     | 0                                       |                |
|         |  |                                       |       |      |               |      | <u></u>          |                             |                       |   |                |
|         |  |                                       |       |      |               |      |                  | Division S                  | ummary - SPECIALTIES  | 310                                     | 0.07           |

|         |  |   |   |          |   |      |   | 1  |  |   |  |
|---------|--|---|---|----------|---|------|---|--|--|---|--|
|         | SUMMARY SHEET  | GSF                                       |   |          | added<br>BOR  |      | added<br>MATERIAL   | SUBCO  | NTRACT   | TOTAL   | 10/23/23 17:22   |
| CODE    | 97,790   | UNIT                                      | QTY   | UNIT     | COST  | UNIT | COST  | UNIT   | COST   | COST  |  |
|         |  |   |   |          |   |      |   |  |  |   | _  |
| Div. 11 | APPLIANCES   |   |   |          |   |      |   |  |  |   | -  |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         | Unit   | ea.                                       | 0   |          | 0   |      | 0   | 6,000  | 0  | 0   |  |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         | Subtotal   | ls  |   |          |   |      |   |  |  |   | 0  |
|         | Bond rate  |   | 0.015   |          |   |      |   | 0  | 0  | 0   |  |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         |  | I   | ı   | ſ        | ĺ   | ĺ    | 1   | Division   | Summary - EQUPIMENT  | 1   | 0.00   |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         |  |   | 1   | 1        | 1   | 1    | 1   | Division   | Summary - MILLWORK   | 0   | 0.00   |
| Div. 13 | SPECIAL CONSTRUCTION   |   |   |          |   |      |   |  |  |   | -  |
| DIV. 13 | SI ESIAE CONSTRUCTION  |   |   |          |   |      |   |  |  |   | -  |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         |  |   |   |          |   |      |   | Division Cummon, CD                                      | ECIAL CONSTRUCTION   |   | 0.00   |
|         |  |   |   |          |   |      |   | Division Summary - SP                                    | ECIAL CONSTRUCTION   | 1   | 1  |
| Div. 14 | CONVEYING SYSTEMS  |   |   |          |   |      |   |  |  |   |  |
|         |  |   |   |          |   |      |   |  |  |   | -  |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         |  |   |   | <u> </u> | l   | l    | <u> </u>  | Division Summary -                                       | CONVEYING SYSTEMS  | 0   | 0.00   |
|         |  |   |   |          |   |      |   | ,  |  |   |  |
| Div. 15 | FIRE PROTECTION  |   |   |          |   |      |   |  |  |   |  |
|         | Fire protection - Units (Wet Pipe)   | le.                                       |   |          | 0   |      | 0   | 0.00   | 0  | 0   |  |
|         | Fire Pump  | ls<br>Is                                  | 0   |          | 0   |      | 0   | 0.00   | 0  |   | 1  |
|         |  |   |   |          |   |      |   | 3.00   |  |   |  |
|         | Subtotal   | ls  |   |          |   |      |   |  |  |   | 0  |
|         | Bond rate  | -   | 0.000   |          |   |      |   | 0  | 0  | 0   |  |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         |  |   |   |          |   |      |   | Division Summa   | ary - FIRE PROTECTION  | 0   | 0.00   |
|         |  |   |   |          |   |      |   |  |  |   |  |
| Div. 15 | PLUMBING   |   |   |          |   |      |   |  |  |   | -  |
|         | Plumbing Fixture   | ea.                                       | 0   |          | 0   |      | 0   | 1,200.00   | 0  | 0   |  |
|         |  |   |   |          |   |      |   | ,  |  |   |  |
|         | Subtotal   | ls  |   |          |   |      |   |  |  |   | 0  |
|         | Bond rate  |   | 0.000   |          |   |      |   | 0  | 0  | 0   |  |
|         |  |   |   |          |   |      |   |  |  |   |  |
|         |  |   |   |          |   |      | 1   | Divisio  | n Summary - PLUMBING   | 0   | 0.00   |
|         | HVAC   |   |   |          |   |      |   |  |  |   |  |
| Div 4E  | IUAC   |   |   |          |   |      |   |  |  |   |  |
| Div. 15 |  |   |   |          |   |      |   |  |  |   |  |
| Div. 15 | HVAC -   | units                                     | 0   |          | 0   |      | 0   | 2,500.00   | 0  | 0   |  |
| Div. 15 | HVAC - Duct work (Duct board)  | ls  | 0   |          | 0   |      | 0   | 775.00   | 775  | 775   |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling  | ls<br>Is                                  | 1 2   |          | 0   |      | 0   | 775.00<br>125.00   | 775<br>250   | 775<br>250  |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans   | ls<br>Is<br>Is                            | 0<br>1<br>2<br>0                                    |          | 0<br>0<br>0   |      | 0   | 775.00<br>125.00<br>0.00                                 | 775<br>250<br>0  | 775<br>250<br>0   |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling  | Is Is Is Is Is                            | 1 2 0   |          | 0   |      | 0 0   | 775.00<br>125.00<br>0.00<br>0.00<br>0.00                 | 775<br>250<br>0<br>0   | 775<br>250<br>0<br>0  |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls  | Is Is Is Is Is                            | 1<br>2<br>0<br>0<br>0                               |          | 0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0   | 775.00<br>125.00<br>0.00<br>0.00<br>0.00<br>0.00         | 775<br>250<br>0<br>0<br>0<br>0   | 775<br>250<br>0<br>0<br>0   |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers  | Is Is Is Is Is Is Is Is Is                | 1<br>2<br>0<br>0<br>0<br>0                          |          | 0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0  | 775.00<br>125.00<br>0.00<br>0.00<br>0.00<br>0.00<br>0.00 | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0                               | 775<br>250<br>0<br>0<br>0<br>0  |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls  | Is Is Is Is Is                            | 1<br>2<br>0<br>0<br>0                               |          | 0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0   | 775.00<br>125.00<br>0.00<br>0.00<br>0.00<br>0.00         | 775<br>250<br>0<br>0<br>0<br>0   | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0  |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty  | Is   Is   Is   Is   Is   Is   Is   Is     | 1<br>2<br>0<br>0<br>0<br>0<br>0                     |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0           | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit   | Is    | 1<br>1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0      |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0           | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)   | Is   Is   Is   Is   Is   Is   Is   Is     | 1<br>1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0      |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  |  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty  | Is   Is   Is   Is   Is   Is   Is   Is     | 1<br>1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0      |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                                    | 1,025  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)   | Is   Is   Is   Is   Is   Is   Is   Is     | 1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                               | 1,025  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)   | Is   Is   Is   Is   Is   Is   Is   Is     | 1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                                    | 1,025  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate   | Is   Is   Is   Is   Is   Is   Is   Is     | 1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0  | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                               | 1,025  |
| Div. 15 | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate   | Is   Is   Is   Is   Is   Is   Is   Is     | 1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                               | 1,025  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL Moving 2x4 lights in ceiling  | Is | 1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 1,025  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL Moving 2x4 lights in ceiling Tactile signage  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 1,025  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture   | Is I  | 1<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>1,025                      | 0.23   |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL Moving 2x4 lights in ceiling Tactile signage  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                                    | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>1,025                      | 0.23   |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  Subtotal  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                                    | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 1,025   | 0.23   |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                                    | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 1,025   | 0.23   |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  Subtotal  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                                    | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775<br>250<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 0.23   |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  Subtotal Bond rate  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0   |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                                    | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 1,025   | 0.23<br>800<br>0.18  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  Subtotal Bond rate  DIRECT COST OVERHEAD COST   | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 0 1,025   | 0.23<br>0.23<br>800<br>0.18<br>65,56   |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  DIRECT COST OVERHEAD COST  SUB-TOTAL  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 1,025   | 0.23<br>0.23<br>800<br>0.18<br>65,56   |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  DIRECT COST OVERHEAD COST  SUB-TOTAL  SUB-TOTAL | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 0 1,025   | 0.23<br>0.23<br>800<br>0.18 65,56<br>included above  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  DIRECT COST OVERHEAD COST  SUB-TOTAL  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 0 1,025   | 0.23  800  0.18  65,56  included above included above  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  Subtotal Bond rate  DIRECT COST OVERHEAD COST  OVERHEAD COST  SUB-TOTAL F.S.S.T - On Materials Only LABOR INS. & TAXES (BURDEN) - On Labor Only   | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 0 1,025 800 0 0 0 83,560  | 0.23  800  0.18  65,56  included above included above  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  DIRECT COST OVERHEAD COST  OVERHEAD COST  SUB-TOTAL F.S.S.T - On Materials Only LABOR INS. & TAXES (BURDEN) - On Labor Only SUB-TOTAL GENERAL LIABILITY & SPI   | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 1,025   | 1,025  0.23  800  0.18  65,50  included above included above                                     |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  Subtotal Bond rate  DIRECT COST OVERHEAD COST  OVERHEAD COST  SUB-TOTAL F.S.S.T - On Materials Only LABOR INS. & TAXES (BURDEN) - On Labor Only   | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 0 1,025  800 0 0 0 0 0 1,025  83,560  83,560  1,210 0               | 0.23  800  0.18  65,50  included above included above  |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  Subtotal Bond rate  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  DIRECT COST OVERHEAD COST  SUB-TOTAL F.S.S.T - On Materials Only LABOR INS. & TAXES (BURDEN) - On Labor Only SUB-TOTAL GENERAL LIABILITY & SPI BUILDER'S RISK INS   | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 800<br>83,560<br>1,210<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0         | 0.23  800  0.18  65,50  included above included above by owner by owner by owner                 |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  DIRECT COST OVERHEAD COST  OVERHEAD COST  SUB-TOTAL F.S.S.T - On Materials Only LABOR INS. & TAXES (BURDEN) - On Labor Only  SUB-TOTAL GENERAL LIABILITY & SPI BUILDER'S RISK INS BUILDING PERMIT & RADON FEE POLLUTION - IMPACT FEES   | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 1,025  800 0 0 0 83,560 11,00 0 0 0 83,560 1,210 0 0 84,770     | 1,025  0.23  800  0.18  65,50  included above included above by owner by owner by owner by owner |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  DIRECT COST OVERHEAD COST  OVERHEAD COST  SUB-TOTAL F.S.S.T - On Materials Only LABOR INS. & TAXES (BURDEN) - On Labor Only SUB-TOTAL GENERAL LIABILITY & SPI BUILDER'S RISK INS BUILDING PERMIT & RADON FEE POLLUTION - IMPACT FEES  PERFORMANCE & PAYMENT BOND                                  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 800<br>83,560<br>84,770<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0        | 0.23  800  0.18  65,56  included above  included above  by owner by owner by owner               |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  DIRECT COST OVERHEAD COST  OVERHEAD COST  SUB-TOTAL F.S.S.T - On Materials Only LABOR INS. & TAXES (BURDEN) - On Labor Only  SUB-TOTAL GENERAL LIABILITY & SPI BUILDER'S RISK INS BUILDING PERMIT & RADON FEE POLLUTION - IMPACT FEES   | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 1,025  800 0 0 0 83,560 11,00 0 0 0 83,560 1,210 0 0 84,770     | 0.23  800  0.18  65,56  included above included above by owner by owner by owner                 |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  Subtotal Bond rate  DIRECT COST OVERHEAD COST  UNE TO Materials Only LABOR INS. & TAXES (BURDEN) - On Labor Only SUB-TOTAL GENERAL LIABILITY & SPI BUILDER'S RISK INS BUILDING PERMIT & RADON FEE POLLUTION - IMPACT FEES  PERFORMANCE & PAYMENT BOND SUB-TOTAL Contingency SUB-TOTAL Contingency | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 800<br>830<br>83,560<br>1,210<br>0<br>84,770<br>0<br>84,770<br>2,543<br>87,313                  | 1,025  0.23  800  0.18  65,56  included above included above by owner by owner by owner by owner |
|         | HVAC - Duct work (Duct board) Diffusers-moving in ceiling Exhaust Fans Test & Balance Air Cooled Make-up Air Units Controls Louvers Heaters Permit Warranty Motorized control dampers (bathrooms & kitchens)  ELECTRICAL  Moving 2x4 lights in ceiling Tactile signage Added 50% new 2x4 light fixture Fire Alarm  Subtotal Bond rate  DIRECT COST OVERHEAD COST  OVERHEAD COST  SUB-TOTAL  GENERAL LIABILITY & SPI BUILDER'S RISK INS BUILDING PERMIT & RADON FEE POLLUTION - IMPACT FEES  PERFORMANCE & PAYMENT BOND  SUB-TOTAL Contingency  | Is I  | 1 1 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0             |          | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 |      | 0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0                | 775.00 125.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00         | 775 250 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0                              | 800 1,025 800 83,560 1,210 0 84,770 0 84,770 2,543 87,313 10,478                                | 1,025  0.23  800  0.18  65,56  included above included above by owner by owner by owner by owner |

10/23/23

| 10/23/23                  | SCHEDULE  |  | 4          | months         |              | weeks    |               | days     |            |  |                |
|---------------------------|---|--|------------|----------------|--------------|----------|---------------|----------|------------|--|----------------|
|                           |   |  |            |                | LA           | ABOR     | MA            | TERIAL   | 0          | THER<br>I  |                |
| CODE                      | ITEM  |  | UNIT       | QUAN.          | UNIT         | COST     | UNIT          | COST     | RATE       | COST   | TOTAL          |
| 1101.00                   | Supervision   |  |            |                |              |          |               |          |            |  |                |
| 1101.01<br>1101.01        | Project Manager (Finishes)                          | 25%<br>0%  |            | 21.00<br>21.00 | 2800<br>2800 |          |               | 0        |            | 0  | 14,700         |
| 1101.01                   | Senior Project Manager Safety Coordinator           | 0%   |            | 17.00          | 1800         |          |               | 0        |            | 0  | 0              |
| 1101.01                   | Superintendent                                      | 50%  |            | 21.00          | 1500         |          |               | 0        |            | 0  | 15,750         |
| 1101.01                   | Assistant Superintendent 1 (Structure)              | 0%   |            | 17.00          | 2000         | 0        |               | 0        |            | 0  | 0              |
| 1101.01                   | Assistant Superintendent 2 (Finishes)               | 0%   |            | 52.00          | 2000         |          |               | 0        |            | 0  | 0              |
| 1101.01                   | Field Engineer                                      | 0%   |            | 17.00          | 1800         |          |               | 0        |            | 0  | 0              |
| 1101.01<br>1101.01        | Unit Finish Coordinator 1 Unit Finish Coordinator 2 | 0%<br>0%   |            | 17.00<br>17.00 | 1500<br>1100 |          |               | 0        |            | 0  | 0              |
| 1101.01                   | Scheduler   | 0%   |            | 17.00          | 1800         |          |               | 0        |            | 0  | 0              |
| 1101.01                   | Labor Foreman                                       | 0%   |            | 50.00          | 1200         |          |               | 0        | 0          |  | 0              |
| 1101.01                   | Material Hoist Operator 1 (Temp)                    | 0%   | wk         | 8.50           | 1000         | 0        |               | 0        | 0          | 0  | 0              |
| 1101.01                   | Material Hoist Operator 2 (Temp)                    | 0%   |            | 8.50           | 1000         |          |               | 0        | 0          | , and the second | 0              |
| 1101.01                   | Field Engineer Helper                               | 0%   |            | 17.00          | 1000         |          |               | 0        |            | 0  | 0              |
| 1101.01<br>1101.01        | Overtime Allowance Travel & Transportation          |  | wk         | 0.00           |              | 0        |               | 0        | 12000      | 0  | not included   |
| 1111.01                   | Labor Burden (Included in unit Cost)                |  | ls<br>Is   | 0.00           |              | 0        |               | 0        | 12000      | 0  | 0              |
|                           |   |  |            |                |              |          |               | · ·      |            |  |                |
| Subtotal                  | Staff   |  |            |                |              | 30,450   |               | 0        |            | 0  | 30,450         |
|                           |   |  |            |                |              |          |               |          |            |  |                |
| 1102.00                   | Layout, Surveys, Contract Documents                 | 1  | I          |                |              | 0        |               | 0        |            | 0  | 0              |
| 1102.01<br>1102.02        | Layout & Engineering                                | 1  | hrs        | 0.00           |              | 0        |               | 0        | 20000      | 0  | 0              |
| 1102.02                   | Corner & Benchmark Surveys Batter Boards            | +  | ls<br>Is   | 0.00           | 2000         |          |               | 0        | 500        | 0  | 0              |
| 1102.04                   | Video Documentation                                 | <u> </u>   | ea         | 0.00           | 2000         | 0        |               | 0        | 8000       | 0  | 0              |
| 1102.05                   | Progress Photos & Aerials                           |  | sets       | 0.00           |              | 0        |               | 0        | 150        | 0  | 0              |
| 1102.06                   | Construction Documents                              |  | ls         | 1.00           |              | 0        |               | 0        | 500        | 500  | 500            |
| 1102.07                   | Shop Drawings, Reproductions                        |  | ls         | 1.00           |              | 0        |               | 0        | 500        | 500  | 500            |
| 1102.08                   | Mailing Cost, Courier                               | 1  | ls         | 0.00           |              | 0        |               | 0        | 3600       | 0  | 0              |
| 1102.09<br><b>1102.11</b> | Pile Driving Logs                                   |  | ls         | 1.00           |              | 0        |               | 0        | 500        | 500  | cost of work   |
|                           | As-Built Drawings Punch List Work                   |  | ls<br>Is   | 1.00           |              | 0        |               | 0        | 500        |  | 500<br>500     |
| 1102.12                   | T dien Elst Work                                    | 1  | 10         | 1.00           |              | <u> </u> | <u> </u>      | <u> </u> | 000        | 000  | 000            |
| 1103.00                   | Temporary Protection and Safety                     |  |            |                |              |          |               |          |            |  |                |
| 1103.01                   | Site Temporary Fencing & Gates                      |  | ls         | 0.00           |              | 0        |               | 0        | 7500       | 0  | 0              |
| 1103.04                   | Traffic Barricades                                  |  | ls         | 0.00           |              | 0        |               | 0        | 2500       | 0  | 0              |
| 1103.08                   | Safety Measures                                     |  | ls         | 0.00           | 2500         |          | 2500          | 0        |            | 0  | 0              |
| 1103.09<br>1103.10        | Handrails & Toe Boards Temporary Stairs             |  | ls<br>Is   | 0.00           | 3500         | 0        | 3500<br>10000 | 0        |            | 0  | 0              |
| 1103.10                   | Ladders   |  | ls<br>Is   | 0.00           |              | 0        | 2000          | 0        | 250        | 0  | 0              |
| 1103.12                   | Scaffolds/Miscellaneous                             |  | ls         | 0.00           |              | 0        | 2000          | 0        | 0          | 0  | cost of work   |
| 1103.13                   | Temporary Signage                                   |  | ls         | 0.00           |              | 0        |               | 0        | 5000       | 0  | 0              |
| 1103.14                   | Fire Extinguishers, etc.                            |  | ea         | 2.00           |              | 0        | 50            | 100      |            | 0  | 100            |
| 1103.15                   | First Aid Supplies                                  |  | wks        | 17.00          |              | 0        |               | 0        | 50         |  | 850            |
| 1103.18                   | OSHA (HRH Safety & Health Systems)                  |  | wks        | 17.00<br>0.00  |              | 0        |               | 0        | 50<br>5000 |  | 850            |
| 1103.20<br>1103.22        | Security Measures Drug Testing                      |  | ls<br>Is   | 0.00           |              | 0        |               | 0        | 3000       | 0  | 0              |
| 1100.22                   | Drug resuing  | 1  | 10         | 0.00           |              | <u> </u> | <u> </u>      | <u> </u> | 0000       |  |                |
| 1104.00                   | Temporary Facilities & Supplies                     |  |            |                |              | 0        |               | 0        |            | 0  | 0              |
| 1104.01                   | Our Field Offices                                   |  | mos        | 0.00           |              | 0        | 1500          | 0        |            | 0  | 0              |
|                           | Copy Machine  |  | mos        | 0.00           |              | 0        | 500           | 0        |            | 0  | 0              |
| 1104.03<br>1104.04        | Fax/Copy/Scanner Machine                            | 1  | ls<br>wks  | 0.00<br>17.00  |              | 0        | 50            | 0<br>850 |            | 0  | 0<br>850       |
|                           | Copy & Fax Paper Office Furniture                   | +  | wks<br>Is  | 0.00           |              | 0        | 5000          | 850      |            | 0  | 850            |
|                           | Office Supplies                                     | <del>                                     </del> | wks        | 17.00          |              | 0        | 75            | 1,275    |            | 0  | 1,275          |
|                           | Architect's/Owner's Field Office                    |  | mos        |                |              | 0        |               | 0        |            | 0  | not in contrac |
|                           | Architect's/Owner's Furniture, etc.                 |  | ls         |                |              | 0        |               | 0        |            | 0  | not in contrac |
| 1104.09                   | Storage Sheds, Trailers                             | 1  | mos        | 0.00           |              | 0        | 500           |          | 2 -        | 0  | 0              |
| 1104.10                   | Technology (7ea)                                    |  | mos        | 0.00           |              | 0        | 1500          | 0        | 2450       | 0  | 0              |
| 1104.11                   | Field Office/Shed Freight & Set-up                  |  | ls         | 0.00           |              | 0        | 1500          | U        |            | 0  | 0              |
| 1105.00                   | Temporary Utilities                                 | <del>                                     </del> |            |                |              |          |               |          |            |  |                |
| 1105.01                   | ,   |  |            |                |              |          |               |          |            |  |                |
| 1105.02                   | Electric Power Cost                                 |  | mos        | 0.00           |              | 0        | 1500          | 0        |            | 0  | 0              |
| 1105.03                   | Start-up Power Cost                                 |  | mos        | 0.00           |              | 0        | 2500          | 0        |            | 0  | 0              |
| 1105.04                   | Temporary Toilets - Office                          | 1  | mos        | 0.00           |              | 0        | 250           |          |            | 0  | 0              |
| 1105.05<br>1105.06        | Temporary Toilets - Jobsite Temporary Water         | +  | mos<br>mos | 0.00           |              | 0        | 350<br>1200   | 0        |            | 0  | 0              |
| 1105.06                   | Drinking Water & Ice                                |  | wks        | 0.00           |              | 0        | 1200          |          |            | 0  | 0              |
|                           |   | 1  |            |                |              |          |               |          |            |  |                |
|                           | Communications                                      |  |            |                |              |          |               |          |            |  |                |
| 1106.01                   | Phone's   | 1  | mos        | 4.00           |              | 0        | 250           |          |            | 0  | 1,000          |
| 1106.02                   | Architect's Phone                                   | 1  | mos        | 2.22           |              | 0        | 4500          | 0        |            | 0  | 0              |
| 1106.03<br>1106.04        | Jobsite Phone Service Fax/DSL Phone Line            | +  | ls<br>mos  | 0.00           |              | 0        | 1500<br>250   | 0        |            | 0  | 0              |
| 1106.04                   | Jobsite Radios                                      | <del> </del>                                     | mos        | 0.00           |              | 0        | 250<br>150    |          |            | 0  | 0              |
| 1106.07                   | Project Sign  | 1  | ls         | 1.00           |              | 0        | 1500          |          |            | 0  | 1,500          |
| 1106.08                   | Bulletin Boards, etc.                               |  | ls         | 1.00           |              | 0        | 500           |          |            | 0  | 500            |
|                           |   |  |            |                |              |          |               |          |            |  |                |
| 1107.00                   | Equipment   | 1  |            |                |              | -        |               |          |            | -  |                |
| 1107.01                   | Project Manager Fuel                                |  | mos        | <u> </u>       |              | 0        | 0             |          |            | 0  | 0              |
| 1107.02                   | Project Engineer Fuel                               | 1  | mos        | <u> </u>       |              | 0        | U             | 0        |            | 0  | 0              |

10/23/23

|                                       |                         | days                                   | 119  | weeks            | 17    | months       | 4         | SCHEDULE   | 10/23/23  |
|---------------------------------------|-------------------------|--|------|------------------|-------|--------------|-----------|--|---|
| OTHER                                 | 01                      | TERIAL                                 | MA   | BOR              | LA    |              |           |  |   |
| RATE COST                             | RATE                    | COST                                   | UNIT | COST             | UNIT  | QUAN.        | UNIT      | ITEM   | CODE  |
| 0                                     | IVAIL                   | 6,000                                  | 1500 | 0                | Olvin | 4.00         | mos       | Superintendent Vehicle/Fuel  | 1107.03   |
| 0                                     |                         | 0                                      | 3000 | 0                |       | 0.00         | mos       | Assistant Superintendent Vehicle/Fuel (2)  | 1107.04   |
| 0                                     |                         | 0                                      |      | 0                |       |              | mos       | Crane Rental, Fuel, etc. additional beyond concrete  | 1107.05   |
| 0                                     |                         | 0                                      |      | 0                |       |              | Is        | Crane Freight & Set-up   | 1107.06   |
| 0                                     |                         | 0                                      |      | 0                |       |              | mos       | Jumps - 2 ea   | 1107.06   |
| 0                                     |                         | 0                                      |      | 0                |       |              | Is        | Crane Foundations & Engineering  |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | wks       | Crane Operation  | 1107.07   |
| 0                                     |                         | 0                                      | 2000 | 0                |       | 0.00         | mos       | Miscellaneous Equipment Rental   |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | mos       | Miscellaneous 3rd Party Equipment Rental   |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls<br>Is  | Miscellaneous Equipment Repair  Miscellaneous Equipment Set-up & Freight   |   |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | mos       | Miscellaneous Equipment Fuel/Lube  |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | mos       | Personnel/Material Hoist Rental - 2 ea   | 1107.13   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Hoist Erection/Dismantle - 2 ea  | 1107.14   |
| 0                                     |                         | 0                                      |      | 0                |       |              | mos       | Jump Hoist - 4 ea  | 1107.15   |
| 0                                     |                         | 0                                      |      | 0                |       |              | mos       | Hoist Operators 2 ea   | 1107.16   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ea        | Hoist Freight In/Out - 2 ea  | 1107.17   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ea        | Hoist Foundations, Enclosures, Ramps - 2 ea  | 1107.18   |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | mos       | Gates  | 1107.18   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Fence  | 1107.18   |
| 0                                     | 10000                   | 0                                      |      | 0                |       | 2.22         | mos       | Temporary Elevator Operators   | 1107.19   |
| 13200 0                               | 13200                   | 0<br>800                               | 200  | 0                |       | 0.00<br>4.00 | each      | Temporary Elevator/Hoist Fees Small Tools/Supplies   | 1107.20<br><b>1107.21</b>                           |
| 0                                     |                         | 0                                      | 4000 | 0                |       | 0.00         | mos<br>Is | Rough Hardware   |   |
|                                       | <u> </u>                | U                                      | 4000 | U                |       | 0.00         | Ιο        | n rough i naruware   | 110/.22   |
| 0                                     |                         | 0                                      |      | 0                |       |              |           | General Clean-up   | 1108.00   |
|                                       |                         | 0                                      |      | 0                | 1600  | 0.00         | wks       | Weekly Clean-up - 2 men week   |   |
| 0                                     |                         | 12,750                                 | 375  | 0                |       | 34.00        | p/u       | Dumpster Rental  |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ea        | Dump Fees  |   |
| 0.5 2,800                             | 0.5                     | 0                                      |      | 0                |       | 5,600        | sf        | Final Clean-up   | 1108.04   |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | ls        | Clean Glass  |   |
| 0                                     |                         | 0                                      | 2000 | 0                |       | 0.00         | fl        | Trash Chute  | 1108.06   |
| 0                                     |                         | 0                                      | 3000 | 0                |       | 0.00         | ls        | Trash Chute Erection/Dismantle   | 1108.07   |
|                                       |                         | 0                                      |      | 0.1              |       |              |           | To estima  | 1100.00   |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | Ic        | Testing Ultra Sonic testing  | <b>1109.00</b><br>1109.01                           |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | ls<br>Is  | Soils Testing  | 1109.01   |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | ls        | Concrete Testing   |   |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | ls        | Masonry Testing  |   |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | ls        | Steel Testing  | 1109.04   |
| 0 0                                   |                         | 0                                      |      | 0                |       |              | ls        | Watertight Testing   | 1109.05   |
|                                       |                         |  |      |                  |       |              |           |  |   |
| 0                                     |                         | 1,734                                  |      | 0                |       | 7%           | ls        | State/Local Sales Tax  | 1111.02   |
|                                       |                         | 22 722                                 |      |                  |       |              |           | la   |   |
| 6,500                                 |                         | 26,509                                 |      | 0                |       |              |           | Construction GC's  | Subtotal  |
|                                       |                         | 0                                      |      | 0                |       |              |           | Face/Parmite   | 1110.00   |
| 0                                     |                         | 0                                      |      | 0                |       | 0.00         | ls        | Fees/Permits Building Permit   |   |
| 0                                     |                         | 0                                      |      | 0                |       | 0.00         | ls        | Pollution Fees   |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Impact Fees  |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Radon Fees   |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Meter Bagging Fees   |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Curb Cut Fees  |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Tap & Meter Fees   | 1110.07   |
| <del></del>                           |                         |  |      |                  |       |              |           |  |   |
| 0                                     |                         |  |      | :                |       |              | 1         | I- "   |   |
|                                       |                         | 0                                      |      | 0                |       |              |           | Insurance  |   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Sub's Protective Insurance   | 1111.05   |
| 0                                     |                         | 0                                      |      | 0                |       |              | ls        | Sub's Protective Insurance Builder's Risk Insurance  | 1111.05<br>1111.06                                  |
| 0<br>0<br>0                           |                         | 0<br>0<br>0                            |      | 0<br>0<br>0      |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance   | 1111.05<br>1111.06<br>1111.07                       |
| 0<br>0<br>0<br>0                      |                         | 0<br>0<br>0                            |      | 0<br>0<br>0      |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance Care/Custody/Hold Harmless/Comp.Oper.Inc.                   | 1111.05<br>1111.06<br>1111.07<br>1111.08            |
| 0<br>0<br>0                           |                         | 0<br>0<br>0                            |      | 0<br>0<br>0      |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance   | 1111.05<br>1111.06<br>1111.07                       |
| 0<br>0<br>0<br>0                      |                         | 0<br>0<br>0                            |      | 0<br>0<br>0      |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance Care/Custody/Hold Harmless/Comp.Oper.Inc.                   | 1111.05<br>1111.06<br>1111.07<br>1111.08            |
| 0<br>0<br>0<br>0                      |                         | 0<br>0<br>0<br>0                       |      | 0<br>0<br>0<br>0 |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance Care/Custody/Hold Harmless/Comp.Oper.Inc. Special Insurance | 1111.05<br>1111.06<br>1111.07<br>1111.08<br>1111.09 |
| 0<br>0<br>0<br>0<br>0                 | Staff                   | 0<br>0<br>0<br>0<br>0                  |      | 0<br>0<br>0<br>0 |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance Care/Custody/Hold Harmless/Comp.Oper.Inc. Special Insurance | 1111.05<br>1111.06<br>1111.07<br>1111.08<br>1111.09 |
| 0<br>0<br>0<br>0<br>0                 |                         | 0<br>0<br>0<br>0<br>0                  |      | 0<br>0<br>0<br>0 |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance Care/Custody/Hold Harmless/Comp.Oper.Inc. Special Insurance | 1111.05<br>1111.06<br>1111.07<br>1111.08<br>1111.09 |
| 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 | Construction Soft Costs | 0 0 0 0 0 0 Subtotal Subtotal Subtotal |      | 0<br>0<br>0<br>0 |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance Care/Custody/Hold Harmless/Comp.Oper.Inc. Special Insurance | 1111.05<br>1111.06<br>1111.07<br>1111.08<br>1111.09 |
| 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 | Construction Soft Costs | 0 0 0 0 0 0 Subtotal Subtotal Subtotal |      | 0<br>0<br>0<br>0 |       |              | ls<br>Is  | Sub's Protective Insurance Builder's Risk Insurance Umbrella Insurance Care/Custody/Hold Harmless/Comp.Oper.Inc. Special Insurance | 1111.05<br>1111.06<br>1111.07<br>1111.08<br>1111.09 |