

From: Jeff Sonne <jeff@floridaecs.net>
Sent: Tuesday, June 2, 2026 9:00 PM
To: Madani, Mo <Mo.Madani@myfloridalicense.com>
Subject: Footnote for R407.2.3(3) Table Entry

[NOTICE] This message comes from a system outside of DBPR. Please exercise caution when clicking on links and/or providing sensitive information. If you have concerns, please contact your Knowledge Champion or the DBPR Helpdesk.

Hi Mo,

This is another item for when there is an opportunity to make 2026 FEC corrections.

For the R407.2.3(3) entry in Table R407.2, there should be a footnote "c" next to the section number as shown in red below (my omission in the original mod).

R407.2.2(4)"	High performance heat pump (Option 2: 16.5 SEER2/8.2 HSPF2)	9	9
R407.2.3(1 or 2) ^c	Efficient water heating	6	6
R407.2.3(3) ^c	Efficient heat pump water heater exhausted to conditioned space	9	9
R407.2.3(4)(a) ^c	Solar hot water heating system (Option 1)	13	13

I don't know if there is still time to make a 2026 correction, but it looks like "Inspection Agency" is missing from the new text in the last paragraph in Section R303.1.3.

Right now it reads:

"...as authorized by an NFRC-licensed independent certification and (IA)."

But it should read:

"...as authorized by an NFRC-licensed independent certification and Inspection Agency (IA)."

Or possibly:

"...as authorized by an NFRC-licensed independent certification and IA."

Thanks,

Jeff

--

Jeff Sonne

Florida Energy Code Specialists, LLC