Playtenet of Marines			des and Standards		Special Occupancy TECHNICAL ADVISORY COMMITTEE All Mods		Page 1 of 11 7/11/2024
	dation Dan			•		Total Mods for this report:	31
TAC Recommen TAC: Special Occ		ding Revie		for Specia	I Occupancy in Pending Review		
		<u></u>					
<u>SubCode:</u> Bu	nd Administrat	lion					
Mod #	Proponent	<u>Chapter</u>	Section	Summa	ry.		Pending Review
11184	Mo Madani	1	110.3.12.1		nresidential buildings in flood hazard areas are proposed I. Proposal concerning this issue.	to be dry floodproofed, several aspects of design	TAC Action
<u>CC #</u>							
S125-22 Part	)						<u>D/IC</u>
Deny / Overlap	Waltz /Flowers	9 Yes – 0 N	0				Staff Classication Overlap
							Ovenap

## 10-Means of Egress

(	Mod #	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
	11064 <u>cc #</u>	Mo Madani	10	1020.2.1	Elevator doors that open into a rated corridor have to meet both the fire partition and fire barrier requirements. The options for elevator door protection in Section 3006.3 would be a viable option, so Section 3006.2.1 could be moved up as Item 6 in Section 3006.2.	TAC Action
	G182-21					
	0eny / Overlap	Flowers / Waltz	9 Yes – 0	No		<u>Staff Classication</u> Overlap
_						

lod #	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
1186	Mo Madani	16	1612.4	This code change does not change the loads used to design breakaway walls. It just shows how the loads expressed using allowable stress design are expressed as ultimate loads, which is used in ASCE 7 for seismic	TAC Action
CC #				design and wind loads.	
6126-22					D/IC
ny / Overla	ap Myers / White	head 9 Yes	s – 0 No		Staff Classication
					<mark>Overlap</mark>

Building Codes and Standards	Special Occupancy TECHNICAL ADVISORY COMMITTEE All Mods	Page 2 o 7/11/2 Total Mods for this report: 31	
ChapterSection303001.2	Special Occupancy in Pending Review      Summary Modifies text of Section 3001.2. The title was modified because this co all people, not just the deaf, hard of hearing and speech impaired.	Pending Rev	

( <u>Mod #</u>	Proponent	<u>Chapter</u>	Section	<u>Summary</u>	Pending Review
11062 <u>cc #</u>	Mo Madani	30	3001.2	This proposal is submitted as there is no new standard published, as of this writing, under the ASME A17.1 in support of IBC 2018 Section 3001.2. This code proposal also provides additional direction and clarification for industry.	TAC Action
G178-21	)				
Deny / Overlap	D Quinn / Whiteh	ead 9 Yes -	- 0 No		Staff Classication
					Overlap

<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
11063	Mo Madani	30	3002.1	The intent of this proposal is consistent terminology for elevator protection. The current text is very inconsistent. This is not intended to have any technical changes.	TAC Action
<u>CC #</u>				This is not intended to have any technical changes.	X AS AS/IC D
G180-21					D/IC
Motion to App	rove / As Submitted	Quinn /	Whitehead	9 Yes – 0 No	Staff Classication
					Correlates Directly

(						Special Occupancy TECHNICAL ADVISORY COMMITTEE All Mods	E		Page 3 of 11 7/11/2024
				des and Standards	-			Total Mods for this report:	31
TAC	Special Occ	upancy	_3	<u>1</u> Total Mode	s for Specia	I Occupancy in Pending Review			
	<u>Mod #</u> 11065 <u>CC #</u> G183-21 Part	<u>Proponent</u> Mo Madani I	<u>Chapter</u> 30	<u>Section</u> 3006	smoke ba	<b>TV</b> t of this proposal is to clarify lobby protection requi arriers. This will also clarify what requirements are er walls of the lobby protection.			Pending Review <u>TAC Action</u> XAS       AS/IC       D         D/IC       D
_	Approve As Su	bmitted Flowers/	Whitehead	9 Yes – 0 nc	)				Staff Classication Correlates Directly

(	<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
	11067	Mo Madani	30	3006.3	Smoke protective curtain assemblies for hoistways are recognized and regulated in NFPA 105 Chapter 9 (2019).	TAC Action
	<u>CC #</u>				There are multiple manufactures of these assemblies in the market. Proposal to address. Definition "SMOKE PROTECTIVE CURTAIN ASSEMBLY FOR HOISTWAY" added.	X AS AS/IC D
	G185-21	)				
- 7	Approve As Su	bmitted Flowers	/ Whitehead	9 Yes – 0 No		Staff Classication
						Correlates Directly
						SS

(	<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	<u>Summary</u>	Pending Review
	11068	Mo Madani	30	3007.6	Adds Exception to Section 3007.6. Concerning "A fire service access elevator lobby is not required to be provided at an occupied roof".	TAC Action
	<u>CC #</u>					AS AS/ICX D
	G187-21					
Ē	Deny / Overlap	Gould / Whitehea	ad 9 Ye	s – 0 No		Staff Classication
F	Готту Demop	oulos - conflicts with	FFPC			Overlap

Florida Medicarea (Marketon)	Building Codes and Standards	Special Occupancy TECHNICAL ADVISORY COMMITTEE All Mods	Total Mods for this report:	Page 4 of 11 7/11/2024 <b>31</b>
TAC: Special Occupancy           Mod #         Proponent           11069         Mo Madan <u>CC #</u> Mo Madan	i 30 3009 The pro- the new		g designers, contractors and building code officials to actual code requirements in ASME A17.1/CSA B44.	Pending Review TAC Action
Deny / Overlap Gould / W	/hitehead 9 Yes- 0 No			Staff Classication Overlap

( <u>Mod #</u>	Proponent	<u>Chapter</u>	Section	<u>Summary</u>	Pending Review
11074	Mo Madani	31	3101.1	Deletes the Section 3114 "PUBLIC USE RESTROOM BUILDINGS IN FLOOD HAZARD AREAS".	TAC Action
<u>CC #</u>					AS AS/ICX [
G194-21	)				D/IC
Deny / Overla	o Gould / White	head 9 Yes-	- 0 No		Staff Classication
Quinn – this w	as deleted from IB	С			Overlap

### 35-Referenced Standards

		<b>A</b> 1	<b>A</b> = + + = = =		
( <u>Mod #</u>	<u>Proponent</u>	<u>Chapter</u>	Section	Summary	Pending Review
11673	Mo Madani	35	35	Modification lists the updated standards in the IBC.	TAC Action
<u>CC #</u>					X <u>AS AS/IC D</u>
ADM52-22					D/IC
Approve / As S	ubmitted Whitehe	ead / Waltz	9 Yes – 0	No	Staff Classication
Belcher – may	be a change to wind	standards	that will need to	be considered.	Correlates Directly

1-Scope and Administration

Chercia Contraction of the second sec	Building Codes and Standards	Special Occupancy TECHNICAL ADVISORY COMMITTEE All Mods	E Total Mods for this report:	Page 5 of 11 7/11/2024 <b>31</b>
TAC: Special Occupancy          Mod #       Proponent         11185       Mo Madani <u>CC #</u> S125-22 Part II         Deny / Overlap       Whitehead / Walter	<u>Chapter</u> <u>Section</u> <u>St</u> 1 109.3.10 Wi are	Special Occupancy in <u>Pending Review</u> ummary /hen nonresidential buildings in flood hazard areas are pro re critical.	posed to be dry floodproofed, several aspects of design	Pending Review TAC Action

### 5-Prescriptive Compliance Method

Mod	#	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
107	705	Mo Madani	5	502.3	This proposal includes requirements for alterations and additions (improvements) to existing buildings in flood hazard areas	TAC Action
<u>CC #</u>	<u> </u>					AS AS/ICX D
EB50	)-22					D/IC
Quinn	- section	numbers are slightly	different f	rom IBC, howev	ver the language is already in the code.	Staff Classication
Deny /	already	in the code Aarons	Whitehea	id 9 Yes – 0 N	lo	Correlates Directly

<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
10706	Mo Madani	5	502.3	Adds requirements to raised foundations for flood requirements	TAC Action
<u>CC #</u>					AS AS/ICX D
EB51-22					D/IC
Deny / Ove	rlap Aarons / Waltz	9 Yes –	0 No		Staff Classication
					<mark>Overlap</mark>
					1

**12-Historic Buildings** 

		Special Occupancy TECHNICAL ADVISORY COMMITTEE		Page 6 of 11 7/11/2024
	Building Codes and Standards	All Mods	Total Mods for this report:	31
TAC: Special Occupancy	<u>31</u> Total Mods for Specia	al Occupancy in Pending Review		
<b>10762</b> <u>CC #</u> EB104-22	vague an	<b>ry</b> and improves the language in Section 1201.2 by prov d unenforceable language	viding a direct pointer to Section 115 and eliminating	Pending Review TAC Action
Deny / Overlap Myers / Whitehead	d 9 Yes – 0 No			Staff Classication Overlap

(	<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
	10763	Mo Madani	12	1201.2	Addresses requirement for a report for Level 1 alteration	TAC Action
	<u>CC #</u>					
l	EB105-22					
j	Deny / Overlap	Phillips / Whitehea	ad 9 Yes	– 0 No		Staff Classication
						Overlap

Mod	#	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
107	766	Mo Madani	12	1203.3	Editorial change to address clarity of section	TAC Action
<u>CC</u> :						
EB1	10-22					D/IC
Deny	/ Overlap	This section does no	ot exist in F	BC Whitehea	ad / Waltz 9 Yes – 0 No	Staff Classication
						Overlap

		Special Occupancy INICAL ADVISORY COMMITTEE		Page 7 of 11 7/11/2024
8 Piblessional Regulation	g Codes and Standards	All Mods	Total Mods for this report:	31
TAC: Special Occupancy	31 Total Mods for Special Occu	ipancy in Pending Review		
Mod # 10767 CC # EB113-22Proponent Mo MadaniChapte Mo MadaniDeny / Overlap This section does not exist in	1205.1 refers users to Se	ection 405.2.1 for nearly all repairs, regardle /es – 0 No	ess of the level of damage	Pending Review TAC Action

(	<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
	10768	Mo Madani	12	1205.1	Editorial change for clarity	TAC Action
	<u>CC #</u>					AS AS/ICX D
	EB114-22					
Ī	Deny / Overlap	Aarons / Whitehea	ad 9 Yes	s 0 No		Staff Classication
						<mark>Overlap</mark>

Mod # 11671 <u>CC #</u>	Proponent Mo Madani	<u>Chapter</u> 12	<u>Section</u> 1203.2	<b>Summary</b> The intent of this code change proposal is to coordinate terminology between the IBC, IFC and IEBC when referring to "automatic sprinkler system" since this term is used and defined in the International Building Code and International Fire Code	Pending Review TAC Action
EB108-22 Deny / Overlap	o Waltz / Whitehe	ead 9 Yes	– 0 No		D/IC Staff Classication Overlap

# <u>SubCode:</u> Residential

## 3-Building Planning

Protection of Register		Building Cod	es and Standards	Special Occupancy TECHNICAL ADVISORY COMMITTEE All Mods	Total Mods for this report:	Page 8 of 11 7/11/2024 <b>31</b>
11398 <u>CC #</u> RB42-22	Proponent Mo Madani	<u>3</u>	1 <u>Total Mods fo</u> Section 301.2.4	Special Occupancy in         Pending Review           Summary         Summary           This proposal makes it clearer that the flood provisions that a or substantially damaged dwellings must comply when locate		Pending Review TAC Action
Approve As Sut	omitted Phillips / \	Whitehead	9 Yes – 0 No	)		Staff Classication Correlates Directly

<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	<u>Summary</u>	Pending Review
11470	Mo Madani	3	321.1.1	Excessive clearances between the car door and the hoistway door on private residence elevators presents a	TAC Action
<u>CC #</u>				serious hazard to young children and slight built adolescents or adults. Proposal to address concern.	AS AS/ICX D
RB135-22	)				D/IC
Deny / Overlag	Myers / Whiteh	nead 9 Yes	; – 0 No		Staff Classication
					Overlap

<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	<u>Summary</u>	Pending Review
11471	Mo Madani	3	322.2.1	The proposal adds provisions to the elevation requirements of Section R322, Flood-Resistant Construction, specifically to allow wet floodproofed accessory structures and detached garages in flood hazard areas with floors	TAC Action
<u>CC #</u>				below the required lowest floor elevations	AS AS/ICX D
RB137-22					
Deny / Overla	p Marrerro / Whit	tehead 9`	Yes – 0 No		Staff Classication
					<mark>Overlap</mark>

Ç	Florida DO CONTRACTOR		Building Coc	des and Standards	Special Occupancy TECHNICAL ADVISORY COMMITTEE All Mods	Total Mods for this report:	Page 9 of 11 7/11/2024 <b>31</b>
TAC:	Special Occu	upancy	<u>31</u>	<u>1</u> <u>Total Mods</u>	for Special Occupancy in Pending Review		
	Mod # 11472 <u>CC #</u> RB138-22	Proponent Mo Madani		<u>Section</u> 322.2.2	<b>Summary</b> FEMA regularly responds to questions about whether utility chas buildings are enclosures. Code change to address this topic.	ases and elevator shafts that extend below elevated	Pending Review TAC Action
	Deny / Overlap Already in FBC		∍head 9 Yes	s – 0 No			Staff Classication Overlap

<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	Summary	Pending Review
11473	Mo Madani	3	322.3.2	Proposal to clarify where the "bottom of the lowest horizontal structural member" is located when applicants elect to use backfilled stem wall foundations so that designers, builders, and building officials can readily determine	TAC Action
<u>CC #</u> RB139-22				compliance.	
		<u> </u>			
Deny / Overla	p Marrero / Whitehe	ad 9 Ye	s – 0 No		Staff Classication
					P

<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	<u>Summary</u>	Pending Review
11474	Mo Madani	3	322.3.3	This proposal requires pilings and columns to be designed in accordance ASCE 24 Flood Resistant Design and Construction, which is the standard of practice for design and construction in flood hazard areas.	TAC Action
<u>CC #</u>					AS AS/ICX D
RB140-22	)				D/IC
Deny / Overla	o Myers / Whiteh	nead 9 Y	′es – 0 No		Staff Classication
					Overlap
1					

		Special Occupancy TECHNICAL ADVISORY COMMITTEE		Page 10 of 11 7/11/2024
	Building Codes and Standards	All Mods	Total Mods for this report:	31
TAC: Special Occupancy	<u>31</u> Total Mods for	Special Occupancy in Pending Review		
Mod #Proponent11475Mo MadaniCC #RB142-22	3 322.3.5	Summary This code change does not change the loads used to design expressed using allowable stress design are expressed as ul design and wind loads.		Pending Review TAC Action
Approve As Submitted Myers / Wh	hitehead 9 Yes – 0 No			Staff Classication Correlates Directly

<u>Mod #</u>	Proponent	<u>Chapter</u>	Section	<u>Summary</u>	Pending Review
11629	Mo Madani	31	3101.5	This proposal is editorial in nature. This proposal is to correct references to section numbers for flood resistance	TAC Action
<u>CC #</u>				requirements.	
RP11-21					D/IC
Approve As Su	bmitted Waltz / V	Vhitehead	9 Yes – 0 No		Staff Classication
					Correlates Directly

### 3318-Light Straw-Clay Construction

(	<u>Mod #</u>	Proponent	<u>Chapter</u>		Summary	Pending Review
	11596	Mo Madani	3318	103.1.1	Adds new Standard AR103.1.1 "Flood hazard areas".	TAC Action
	<u>CC #</u>					X AS AS/IC D
	RB302-22					
4	Approve As Su	bmitted Waltz / V	Vhitehead	9 Yes – 0 No		Staff Classication
						Correlates Directly
						·



# Special Occupancy

**TECHNICAL ADVISORY COMMITTEE** 

All Mods

Page 11 of 11 7/11/2024

Total Mods for this report: 31

Mod #	Proponent	<u>Chapter</u>	Section	<u>Summary</u>	Pending R
11597	Mo Madani	3319	101.3	Adds new Section AS101.3 "Flood hazard areas".	TAC Action
<u>CC #</u>					X AS AS/IC
RB304-22					
pprove As S	Submitted Phillips	/ Whitehead	9 Yes – 0 No	0	Staff Classica
	•				Correlates Dire

#### Search Criteria

Modification #:	ALL	Code Version:	2026
Code Change Cycle:	2026 ICC Code Change Original Modification	Sub Code:	ALL
Chapter & Topic:	ALL	Section:	ALL
Date Submitted From:	ALL	Date Submitted To:	ALL
TAC:	SP	TAC Recommendation:	ALL
Commission Action:	ALL	Modification Status:	Verified
Proponent Last Name:	ALL	Proponent First Name:	ALL
Text of Modification:	ALL	Related Modifications:	ALL
Affects HVHZ:	ALL	Archived:	No