

LISTING INFORMATION OF Air Louvers VLFEZ-HRC Vision Frame

SPEC ID: 32787

Air Louvers, Inc. 6285 Randolph St. Commerce, CA 90040 United States

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service is or has ever been under an Intertek certification program.

LISTING INFORMATION

WINDSTORM RESISTANT PRODUCTS & COMPONENTS Model VLFEZ-HRC Hurricane Vision Frame Door: Single out-swing only, 1-3/4" door, Max 3070 Maximum Size: 24" x 62" DP Rating (psf): 55 Impact Resistance: 350 ft-lbs, Missle D, Wind Zone 4 * Vision Frame must be installed in a listed windstorm resistant door.

* All doors/walls/components must be rated and listed accordingly.

This specification confirms the VLFEZ-HRC Vision Frame is manufactured under a program of follow-up inspections conducted by Intertek. The inspections verify the products are manufactured in a manner consistent with the submitted quality system documentation.

Product	Product Approval No.
VLFEZ-HRC Vision Frame	FL# 13187

Attribute	Value
Criteria	ASTM E330 (2002)
Criteria	ASTM E1886 (2002)
Criteria	ASTM E1996 (2003)
Criteria	ANSI A250.13 (2003)
Criteria	TAS 203
Criteria	TAS 201
Criteria	TAS 202
Criteria	ASTM E1886 (2005)
Criteria	ASTM E1996 (2005)
Criteria	ANSI A250.13 (2005)
CSI Code	08 11 00 Metal Doors and Frames
DP Rating (psf)	55
Hurricane Impact Load Rating ft-Ib	350
Impact Missile Level	Level D
Intertek Services	Certification
Listed or Inspected	LISTED
Listing Section	WINDSTORM - GLAZING SYSTEMS
Report Number	3116736-001, 102516327MID-001
Spec ID	32787
Verification Testing	No