



August 12, 2017

Florida Department of Business and Professional Regulation
1940 North Monroe Street, Tallahassee FL 32399

Regarding: Structall Building Systems, Inc.
Structural EPS Foam Core Wall Panels (Steel Skin)
15-2937

To Whom It May Concern:

This office has reviewed test reports showing structural performance of the above-noted product. These test reports pertain to testing performed in accordance with ASTM E72-98, ASTM E72-02 & ASTM E72-05 Standard Test Methods of Conducting Strength Tests of Panels for Building Construction as well as ASTM E564-06 Standard Practice for Static Load Test for Shear Resistance of Framed Walls for Buildings. These standards have not been adopted in the Florida Building Code Sixth Edition (2017), but serves as an applicable test method in accordance with sections 104.11.2 & 1708.3 for the purpose of determining structural performance of this product.

This office has also reviewed test reports showing burn characteristics of the above-noted product. These test reports pertain to testing performed in accordance with ASTM E84-91 Test Method for Surface Burning Characteristics of Building Materials. This standard is not adopted in the Florida Building Code Sixth Edition (2017), but this Test method is equivalent to ASTM E84-13A which is adopted in the Florida Building Code Sixth Edition (2017)

Respectfully,

AUG 16 2017

Frank L. Bennardo, P.E.
Frank L. Bennardo, P.E., Inc.
FL PE 0046549
Cert of Auth #9885

