

Exhibit B - Porter Mansion Photographs

1. Exterior Images for Entries



Photo 1 - Existing front Entry 2020



Photo 2 – Front Entry 1981



Photo 3 – Current South Elevation 2020



Photo 4 – Existing South Rear Entry

2. Interior Stairs



Photo 5 –
Grand Staircase
Connecting Levels 1
and 2



Photo 6 – Secondary Internal Stair connecting
levels 1 to 2



Photo 7 – Secondary Internal Stair – Connecting Level 2 to Attic



Photo 8 – Secondary Internal Stair – View from Attic

3. Existing Restrooms



Photo 9 – Women's Restroom Level 1 –
Non-Ada Compliant



Photo 10 – Men's Restrooms Level 1
Non-Ada Compliant



Photo 11 – Level 2 Water Cooler
Non-Ada Compliant



Photo 12 – Level 2 Men's Restrooms
Level 2 Does not have any Women's Restrooms



Photo 13 – Attic Level Women's Toilet Room



Photo 14 – Attic Men's Toilet Room



Photo 15 – Basement Level Men’s Restroom
Non-Ada Compliant



Photo 16 – Basement Level Women’s Restroom
Non-Ada Compliant



Photo 17 – Existing North Façade



Photo 18 – Existing North Facade



Photo 19 – Existing door hardware at south entrance



Photo 20 – Internal Stair connecting to Basement, added 1981

