

Invoice Revised

Date: August 9, 2023 RECEIPT # 2270 R

1820 LLC, #101 1820 Miami FL, 33129 BB2017002342

Payment Method
Tentative timeline
Job

50% commencement 35% after duct work and 15% Final

1st Floor retail area and office
Vanella – Post repair

Qty.	Description	Price	1st %	Total
	General Description:			
	Provide reinforced concrete encasement for all six steel columns. Provide a 1-hour fire-rated ceiling for retail area (2980 SF)			42,890
	Unit #101 & #102 exterior area (see below for location) fill with concrete approximately 4 yards of concrete in exit stairs resolving the issue of illegal steps in the stairs going to the second floor also resolving the issue of the electrical room existing (too small) converting it into a subpanel room./ storage. Creating an opening in the small room (101) connecting the bathroom area with the secondary exit. 3rd moving the existing door two feet forward in order to expand the space of the new subpanel room.			\$6,986
	Need new metal door outside in the new emergency exit –custom made. Non-standard opening + installation separating unit #101 and #102			\$1,700
	Structure and plumbing: build all bathrooms, \$6000 each with tile flooring, all included hardware, toilets, mirrors and vanities (walls will not be tiled, additional).			\$12,000
	Build a new bathroom in #102 – plans needed (App.)			\$7,580
	Disposed of old unit and relocate brand new AC unit, 5 ton, including all materials, duct work and 10 drops + aluminum grills 10"x8" for unit #0 second floor			\$11,862
	Add water heater systems (1) for #101+102 and the other for Unit#0 tankless). Installation and unit. We will try to re-use and existing water tank			\$2,440
Opt A.	Remove electrical panel from the second floor and move it to the first floor in the old electrical room. This include move the electricity of the new AC unit to the first floor.			\$3,460
	Re structure Electrical room and enclosed building a wall as well as closed existing exit so we can expand the electrical room underneath the stairs – costume door included			\$3,989
	Repair middle wall and remove all the electrical conduits existing so there is access from unit #1 to the new exit through the new door – add a new door			\$3,290

drainage 4" higher and reinforce the toilet and sink do not follow the Flori	ore toilet/ sink (we had to change the e wall again – plumbing and drywall – da building Code. Visit unit #2 and #3, (3 and clean -replace Ac brackers in Unit floor manually.	Unit1 and 2		2,650
32"x 6'x 8" and a 36" x 6'x 8" Build fr	am, build its bore, and hinges- no paint om scratch. And door knob. Installation Thermo fan of 8" tape mastic. 20x20 roof tallation.			\$13,490
Installation of glass door and purch	ase			\$4,800
building as well as add a New Pane	or for 1820 and new wiring for existing I for unit #2, first floor in unit "B". Repair of Demo. Install sheetrock throughout and vell as add the ceiling.			\$12,890
All work to be completed in a workmanlike manner according to standard practices. Any afteration or deviation from specifications above involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate. The above work does not include any structural repairs below the roof deck, air conditioning, electrical, satellife, etc. of said items or related items not directly related to the installation of the roof. Any damages caused by any third portry, such as installation of new AC units or repairs done by any portry without written authorization from Gator Roofing & Const. will not be covered by the company's I year warranty on work performed and or maintenance agreement. Our workers are fully covered by Workmen's Compensation Insurance. Warranty is effective from the date of this contract- I year limited warranty against leaks due to workmanship. EXCEPTIONS: I). Any damages caused by acts of nature i.e. hurricanes, tomados, wind storms, must be paid by owners insurance. Replacements of any part of the roofing system, or flashing not performed by anyone who is not authorized agent of Gator Roofing & Construction, LLC. 2) Gator Roofing & Construction LLC, shall nativest, or consequential loss of contents or profits or any other incidental, general, special, or compensatory damages to anyone. 3). Claims must be reported to Gator Roofing & Construction, LLC. In writing within 30 days after discovery of nonconformance, rupture, perforation, or structural failing, and Gator Roofing & Construction, LLC. In opportunity (no less than 30 days of notification), to inspect the roofing, flashings in claims. Adequate information must be submitted with claim including date of installation, proposal Number, a copy of this document must be presented at time of claim.			Subtotal #1 Total	\$96,197 \$33,830 \$130,027