



Corporate Offices / Laboratories

297 Buell Road
Rochester, NY 14624
(585) 328-7668
Fax: (585) 328-7777

ETC Laboratories

Measuring Up To Your Standards And More

Report Number: ETC-08-1014-21317.0

Test Start Date: 01/16/2009

Test Finish Date: 01/20/2009

Report Date: 01/21/2009

Dade County Notification Number: ETC09003

TAS 201, TAS 202, TAS 203 Combined Test Report

Rendered To:

Four Seasons Solar Products
5005 Veterans Memorial Highway
Holbrook, NY 11741


Hurricane Impact Roof Window

Summary of Results

Item	Unit	
Overall Design Pressure, Pos./Neg.	psf	70.00
Air Leakage Rate	sfcfm/ft ²	0.01
Maximum Water Pressure Achieved	psf	10.50
Maximum Structural Pressure Achieved, Pos./Neg.	psf	105.00
Missile Resisted	-	Large
Nominal Missile Speed Resisted	ft/sec	50.00
Maximum Cyclic Pressure Achieved Pos./Neg.	psf	70.00
FER Test	-	Pass

Summary Description:

The tested unit was a fixed aluminum roof window constructed with mechanically fastened frame corners. Three specimens of identical construction were tested, measuring 39-3/8 in. wide by 66 inches high by 6-1/2 inches deep. The IG unit used had a nominal thickness of 7/8 inch an exterior lite of 1/8 inch tempered glass and an interior lite consisting of 1/8 inch annealed glass to either face of a 0.090 inch PVB interlayer and glazed with DOW 995.


Joseph Labora Doldan, P.E.
Florida P.E. #42929

6-03-09

Test Specifications

The testing was conducted in accordance with Florida Building Code test Protocols for High Velocity Hurricane Zones TAS 201-94, TAS 202-94 and TAS 203-94 without deviations.

Note: Safety glass permanent marker identified before testing began

TAS 202-04 Results




Specimen 1	<u>Results</u>	<u>Allowed</u>
1. Air Infiltration Test – ASTM E283 @ 1.57 psf	0.01 scfm/ft ²	0.3 scfm/ft ²
2. Uniform Static Air Pressure Test - ASTM E 330 Design Pressure – 70.00 psf Design Load: 70.0 psf (100% x DP)		
Center of rafter, between fasteners		
Positive Deflection	0.059 in.	0.366 in. (L/180)
Negative Deflection	0.081 in.	0.366 in. (L/180)
3. Water Resistance Test – ASTM E331 Design Pressure – 70.00 psf Test pressure – 10.50 psf	Pass	No Leakage
Water spray was delivered to the specimen and maintained a rate of 5 gallons per hour per square foot of specimen area for the duration of the water resistance test.		
No water infiltration past the inner most plane of the test specimen occurred during the water resistance test.		
4. Uniform Static Air Pressure Test - ASTM E 330 Design Pressure – 70.00 psf Full Test Load: 105.00 psf (150% x DP)		
Center of rafter, between fasteners		
Positive Permanent Set	0.014 in.	0.264 in. (.4%)
Negative Permanent Set	0.031 in.	0.264 in. (.4%)
5. Forced Entry Resistance – ASTM F588 Grade: 10		
Disassembly Test	Pass	No Entry
Sash Manipulation Test	Pass	No Entry

Test notes:

The specimen remained in place throughout the tests and no damage to the fasteners was observed.

The specimen successfully completed all testing as prescribed by Test Protocol TAS 202-94 and the associated Frequently Asked Questions and sections of the Florida Building Code. No change in the specimen was observed that could be indicative of incipient failure.


 Joseph Labora Doldan, P.E.
 Florida P.E. #42929
6-03-09

TAS 201-04 & 203-04 Test Results**Specimen 1****Specimen 2****Specimen 3**

Notes: The circles on the diagrams above indicate the impact locations for that specimen.

The X measurement stated below is taken from the left edge of the specimen,

The Y measurement stated below is taken from the top edge of the specimen.

The large missile used was a piece of #2 southern yellow pine, 2 x 4 dimensional lumber, 97 inches long and weighing 9.2 lbs.

Impact Location	Missile Speed (ft/sec)	X Measurement (in.)	Y Measurement (in.)
Specimen 1			
Center of Glass	49.9	20	32
Lower left glass corner	49.8	7-1/2	57
Specimen 2			
Center of glass	50.3	19-1/2	33
Lower left glass corner	51.8	9	57
Specimen 3			
Center of Glass	50.4	19	32
Lower left glass corner	49.8	8-1/2	56-1/2

Cyclic Wind Pressure Loading Tests:

Notes: The specimen was subjected to pressure cycles of the same sequences, duration and pressure differentials stated below in the Tabulation of Pressure Differences

The maximum inward and outward acting pressures exerted on the specimens were equivalent to the design pressures stated below in the Tabulation of Pressure Differences.

The maximum deflection and permanent set were recorded using a straight edge and steel scale and represent the average deflection over several cycles at maximum pressure differential and the difference between measurements taken before cycling and after cycling respectively.

Joseph Labora Doldan, P.E.
Florida P.E. #42929

6-03-09

TAS 201-04 & 203-04 Tests Results (cont.)

Tabulation of Pressure Differences:

Number of Cycles	Pressure Range of Cycles Inward Acting Cycles -DP = 70.00 psf				Specimen 1	Specimen 2	Specimen 3
	% of DP	Pa (psf)	% of DP	Pa (psf)	(sec/cycle)		
3500	20	14.0	50	35.0	2.6	2.0	2.0
300	0	0.0	60	42.0	2.6	4.2	4.2
600	50	35.0	80	56.0	2.9	1.4	1.4
100	30	21.0	100	70.0	2.6	2.6	2.6
Number of Cycles	Pressure Range of Cycles Outward Acting Cycles -DP = 70.00 psf				Specimen 1	Specimen 2	Specimen 3
					(sec/cycle)		
50	30	21.0	100	70.0	3.0	3.0	3.0
1050	50	35.0	80	56.0	2.6	2.0	2.0
50	0	0.0	60	42.0	2.7	3.4	3.4
3350	20	14.0	50	35.0	2.3	2.0	2.0

Maximum Deflection and Permanent Set from Pressure Cycling:

Location of Measurement		Cycle	Maximum Deflection (in.)	Permanent Set (in.)
Specimen 1	Between rafter fasteners	Inward Acting Pressure	0	0
		Outward Acting Pressure	0	0
Specimen 2	Between rafter fasteners	Inward Acting Pressure	0	0
		Outward Acting Pressure	0	0
Specimen 3	Between rafter fasteners	Inward Acting Pressure	0	0
		Outward Acting Pressure	0	0

Condition of Test Specimens:

The specimens remained in place throughout the tests and no damage to the fasteners was observed.

After testing, the specimens exhibited many fractures to the impacted light of glass.

These specimens average recovery over maximum deflection was 100%.

All three specimens passed impact with no missile penetration and no openings after cyclic testing.

No change in the specimen was observed that could be indicative of incipient failure.



Joseph Labora Doldan, P.E.
Florida P.E. #42929
G-03-09

Product Description of Test Specimen

Specimen Item	Laboratory Verification
<u>Frame:</u>	
Model/Series	Hurricane Impact Roof Window
Size	39-3/8 in. W. x 66 in. H. x 6-1/2 in. D.
Daylight Opening	34-7/8 in. W. x 61-1/2 in. H.
Material	Aluminum
Construction	Two aluminum rafters 2 in. W. x 5 in. D. x 66 in. high forms the sides. The rafters have [2] 3 legged rubber fins set into extruded T-slot profiles on their top edge. Extruded aluminum muntins (38-3/4 inches) wide are laid on top of the rafters (horizontally) forming top and bottom members, they are fastened at each corner with [2] 10-24 x 3/8 in. machine screws. Aluminum end cover plates 4-1/2 in. D. x 1/8 in. thick are bent at 90 degree angles at either end and the newly formed 1-1/4 inch legs are inserted into the interior ends of the rafters against their outer edges, [2] #8 x 1 in. L. self drilling pan heads are driven horizontally from exterior lateral edges of rafter, 1/2 in. from ends and spaced 3 in. apart into legs of cover plate securing its position.
<u>Glazing:</u>	
Overall IG thickness	7/8 in. glass from Cardinal
Thickness of lites	Exterior – 1/8 in. tempered Interior – 1/8 in. ann. / 0.090 in. PVB / 1/8 in. ann.
Interlayer	0.090 in. PVB, Cardinal, Sea Storm
Number of lites	2
Spacer ID	SS-D
<u>Glazing Method:</u>	
Type	IG sets on top of frame from exterior, compressing 3 legged rubber fins on top edge of vertical rafters and sealed with a cap bead of DOW 995 structural sealant to the interior and exterior edge of the rafters. An aluminum glazing cap with 3 legged rubber fin facing the IG is placed to the exterior and fastened with [7] #10 x 1-1/2 in. L. screws with bushings located 3 in. from ends and spaced on 10 in. centers driven from the exterior, with a snap in aluminum beauty cap covering screws the full length of either rafter.



Joseph Labora Doldan
 Joseph Labora Doldan, P.E.
 Florida P.E. #42929
 6-03-09

Product Description of Test Specimen

Specimen Item	Laboratory Verification
<u>Glazing Method (con't):</u>	IG unit is sealed to the horizontal muntin bars with dual sided glazing tape 3/8 in. W, x 1/16 in. D. and DOW 995 structural sealant to the edge of the IG and the interior face. An aluminum muntin cap with single sided glazing tape 3/8 in. W, x 1/16 in. D. facing the IG is set on top of unit sandwiching a 5/16 in. W. x 3/16 in. H. x 36 in. L. pieces of steel stock, [11] 10-24 x 3/4 in. machine screws with bushings, located 2-1/2 in. from ends, then 3-1/16 in on center spacing are driven from the interior of the muntin bars through the steel stock and into the pocket of the muntin caps completing the fastening, with a snap in vinyl cap covering screw heads the full width of either muntin. A 7/8 in. square wood spacer is placed along the exterior perimeter of the unit and sandwiched in position; imitating additional IG units if this were a complete roof system.
Bite depth	1/2 in.
<u>Reinforcement:</u>	5/16 in. W. x 3/16 in. H. x 36 in. L. steel stock centered in muntin bars
<u>Weather-stripping:</u>	[2] Rows of rubber compression seal with 3 legs, 0.365 in. W. x 0.265 in. H. with a 0.187 in. T-extrusion on bottom face of each glazing cap [2] Rows of rubber compression seal with 3 legs, 0.365 in. W. x 0.265 in. H. with a 0.187 in. T-extrusion on top face of rafters
<u>Drainage:</u>	[2] oval slots 7/16 in. W. X 3/16 in. D. through ends of muntin bar at rafter intersection
<u>Test Buck:</u>	
Mounting Gap	0 in. at the head, jambs and sill
Shims	Located on lateral edges of rafters, see test buck drawing
Sealant	Silicone
Material	2 x 6, SPF, #2
<u>Anchorage of Frame to Test Buck:</u>	
Type	1/4 in. x 2-1/2 in. L. lag bolt
Quantity	[2] at each corner, horizontal orientation
Location	1-1/4 in. from ends of rafters, spaced 2-3/8 in. apart

Joseph Labora Doldan
 Joseph Labora Doldan, P.E.
 Florida P.E. #42929

6-03-09

Statement of Compliance: The results of the testing demonstrate the products tested Meets the requirements of Chapters 1606, 1619 and 1626 of the Florida Building Code and the requirements of Florida Building Code test Protocols for High Velocity Hurricane Zones TAS 201-94, TAS 202-94 and TAS 203-94

Review of Bill of Materials: As Supplied

Review of Assembly and Detail Drawings: Plan view, Rafter section, Muntin assembly 2 pages, Steel stock, Bucking, Glazing cap, Rafter, Muntin, Beauty cap, Muntin cap.

Components changed or altered during testing to achieve stated results - None

This report, in its original form contains product drawings and a Bill of Materials.

Persons Witnessing Tests:

Joe Doldan, PE.
Josh Reindl, ETC Laboratories
Mark Sennett, ETC laboratories
Gurjinder Singh Dhami, ETC Laboratories

Joseph Labora Doldan
Joseph Labora Doldan, P.E.
Florida P.E. #42929
6-03-09

Conditions, Terms, and General Notes Regarding These Tests

The product tested Has Been compared to the detailed drawings, bill of materials and fabrication information supplied by the client so named herein. Our analysis, which includes dimensional and component description comparisons, indicate the tested product and engineering information supplied by the client "Are Equivalent". The report and representative samples will be retained for four years from the date of initial test.

These test results were obtained by employing all requirements of the designated test methods with no deviations. The test results and specimen supplied for testing are in compliance with the referenced specifications. The test results are specific to the product tested by this laboratory and of the sample supplied by the client named herein, and they relate to no other product either manufactured by the client, a Fabricator of the client or of installed field performance.

This report does not constitute a certified product. The program administrator may only grant product certification.

ETC Laboratories makes no opinions or endorsements regarding this product and its performance. This report may not be reproduced or quoted in partial form without the expressed written approval of ETC Laboratories.

ETC Laboratories letters, reports, its name or insignia or mark are for the exclusive use of the client so named herein and any other use is strictly prohibited. The report, letters and the name of ETC Laboratories, its seal or mark shall not be used in any circumstance to the general public or in any advertising.

Limitation of Liability: Due diligence was used in rendering this professional opinion. By acceptance of this report, this client agrees to hold harmless and indemnify ETC Laboratories, its employees and offices and owners against all claims and demands of any kind whatsoever, which arise out of or in any manner connected with the performance of work referred to herein.


Revision History

Date	Rev. #	Pages Affected	Revisions
01/21/09	.0	N/A	Original report issue

For ETC Laboratories

Josh Reindl, Testing Technician


Mark Sennett, Senior Test Technician


Gurjinder Singh Dhami, Director of Testing
Person in Responsible Charge


Joseph Labora Doldan, P.E.
Florida P.E. #42929
6-03-09

ETC Laboratories ETC-08-1014-21317
Report #: 04/10/2009
Date:
Verified By: M.S.

ETC Laboratories


ETC-08-1014-21317

04/10/2009

E.C.O. #	REV.	DESCRIPTION:	DATE APPROVED
	A	INITIAL RELEASE AS SINGLE LITE ONLY (7 GIG)	03/25/06
	B	MONTH LENGTHS CHANGED FROM 30-31-31 TO 30-30-30	03/25/06

HV11ZTEST5B05 - BILL OF MATERIALS

HVHZTESTSLS5 - BILL OF MATERIALS			
PART NUMBER	DESCRIPTION	QTY.	
1 AW5IB506GF	5" RAFTER BAR, GG 1/16"	2	
2 AW5GC06GF	EXTRD ALUM. GLAZING CAP, GG 1/16"	2	
3 AW4BC06GF	EXTRD ALUM. BEAUTY CAP, GG 1/16"	2	
4 RX5NGL288U	FIN GLAZING CHORD 4-PART	1	
5 HN200A-36	#10-24 x 1 1/2" PP MS NS	2	
6 CN4201	THERMAL BREAK BUSHING-BAG OF 100	1	
7 -----	7/8" x 7/8" x 64" LONG WOOD BLOCK	2	
8 AW4MNB039F	EXTRD ALUM. MUNTIN CAP, 3/8"	2	
9 AW4MTB039F	EXTRD ALUM. MUNTIN, 38-3/4"	2	
10 HK1023B-12	BL H-SETTING BLOCK	1	
11 HK1009ACR	1/16" THK x 3(6) x 40FT GLAZING TAPE	1	
12 HN2008-20	#10-24 x 3/4" PP MS NS	2	
13 RW4M1037F	EXT RD RUBBER MUNTIN COVER	5	
14 HN2011-20	#10-24 x 3/8" PP MS NS	20	
15 CX679371001G	3/8" x 63" x 7(8) O.80 LAMI GLASS	1	
16 SeaStorm	1090" PBB by Cardinal	1	
17 -----	DOW 995 STRUCTURAL SEALANT, 5M. TUBE	2	
18 8895KG7	5/16" x 3/16" G x 36" LNG. 5 STEEL STOCK	2	
19 -----	36-7/8" x 5" x 1 1/8" THK ALUM. SHEET		




PROPRIETARY CONTENTS		THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOIL PROPERTY OF FOUR SEASONS SOLAR PRODUCTS, LLC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF FOUR SEASONS SOLAR PRODUCTS, LLC, IS PROHIBITED.		HURRICANE IMPACT ROOF GLASS TEST BUILD	
TO/BETWEEN:		NAME:		DATE:	
McGEE, INC.	McGEE, INC.	DRAWMER, RL	01/22/2017		
McGEE, INC.	McGEE, INC.	CHECKED BY:			
McGEE, INC.	McGEE, INC.	ENG. APPROV'D:			
McGEE, INC.	McGEE, INC.	W.M. ALFR.			
McGEE, INC.	McGEE, INC.	O.C.:			
MATERIALS:		DO NOT SCALE DRAWING			
5005 VETERANS MEMORIAL HIGHWAY ILLOQUIS, NY 11741 PHONE: (631) 563-4000 FAX: (631) 216-9041					
FILE: TNA# B-7-625					

1 5/16" APPROX
TO C/L OF
RAFTER, T.F.

ETC Laboratories
Report #: ETC-08-1014-21317
Verified By: M.S.

Date: 04/10/2009




(1) RAFTER SECTION
S1E 1/4" T-4

(2) RAFTER SECTION
S1E 1/4" T-4

ECO #:	REV.:	DESCRIPTION:	DATE APPROVED:
	A	ORIG. RELEASE	3/25/08
	B	NOTES: SEALANT DETAIL UPDATED	05/01/08


Four Seasons Sunrooms Outdoor Living Indoors	
1100 Veterans Memorial Highway Rockwood, NY 14771 Phone: (631) 452-4000 Fax: (631) 216-8676	
SIZE: FILE NAME: B	SCALE: 1:2 PAGE: 2
PROPRIETARY AND CONFIDENTIAL: THE INFORMATION CONTAINED HEREIN IS THE SOLE PROPERTY OF FOUR SEASONS SOLAR PRODUCTS, LLC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF FOUR SEASONS SOLAR PRODUCTS, LLC, IS PROHIBITED. © 2008 FOUR SEASONS SOLAR PRODUCTS, LLC.	NAME: DATE: 03/25/08 CHECKED BY: J. RL ENG. APPR: M. S. MFG. APPR: C. S. W.L. WEBB DRAWING NO. 0000 DO NOT SCALE DRAWING DESCRIPTION: HURRICANE IMPACT GLASS TEST BUILD

ETC Laboratories Report #: ETC-08-1014-21317
 Verified By: MJ Date: 04/10/2009



ETC Laboratories, Report #: ETC-08-1014-21317
Verified By: MJS Date: 04/10/2009

E.C.O. #: REV.	DESCRIPTION:	DATE:	APPROVED
A	ORIGINAL RELEASE	3/28/08	




ETC Laboratories Report #: ETC-08-1014-21317
Verified By: M.S. Date: 04/10/2009

ETC Laboratories Report #: ETC-08-1014-21317

Verified By: M.S. Date: 04/10/2009

T.C.O. #:	REV.	DESCRIPTION:	DATE:
	A	ORIGINAL RELEASE	05/16/08



1 STEEL INSERT
SCALE 3' = 1'-0"


NOTES

- NOTES

 1. MATERIAL IS: W1 TOOL STEEL, MCMASTER-CARR PNR: 6895K67
 2. PART MUST BE PAINTED AFTER DRILLING TO PREVENT CORROSION.

卷之三

ETC Laboratories Report #: ETC-08-1014-21317
 Verified By: _____ Date: 04/10/2009



(1) Rafter Section
SCALE: 6'-1-0"


(2) Rafter Section
SCALE: 6'-1-0"

1 TEST BUCKLING
SCALE: 3" = 1'-0"

ETC Laboratories	Report #:	ETC-08-1014-21317	
Verified By:	<i>M S</i>	Date:	04/10/2009

AS - 0918 / 01000
 This is not an Astro drawing. It is Astro's interpretation of the section design. Please check the drawing and let the design before using AS ASTRO ACCEPTS NO LIABILITY FOR THE PERFORMANCE OF GOODS OR PRODUCTS PRODUCED THEREFROM. ASTRO MAKES NO WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. THIS DRAWING, ASTRO'S ONLY WARRANTY SHALL BE AS STATED ON ASTRO'S SALES AGREEMENT FORM.

AS - 0918 / 01000
 STANDARD COMMERCIAL TOLERANCES FOR EXTRUDED BAR 8265
 AS REF. NO. AND SHAPES APPLY UNLESS SPECIFICALLY SHOWN OTHERWISE
 ASTRO DIE NO. 8265
 ASTRO DIE NO.



ASTRO SHAPES, INC.			
65 MAIN STREET STRUTHERS, OHIO 44471			
DESCRIPTION 2 1/8" GLAZING CAP			
SCALE	2=1	DRAWN L.L.	DATE 08/21/97
REVISIIONS	CUSTOMER FOUR SEASONS SOLAR STATE NY		
REVISIONS	CUST. PART NO. 5GC		

- (*) INDICATES 0.015 R (8)
- (*) INDICATES 0.040 R (8)
- (o) INDICATES 0.100 R (2)
- ALL UNSPECIFIED CORNERS & FILLETS TO BE 0.060 IN.
- PRIMARY ALLOY & TEMP/PR : 6063-T5

Revision 0 02/24/98 Approved Number 56216-801
 TITLE BLOCK TS0002 02/24/98

ETC Laboratories
Report #: ETC-08-1014-21317
Verified By: MJS


Date: 04/10/2009

AS - 08075 / 0300 This is not an Astro design. It is Astro's interpretation of the section designed and requested by its customer. Customer should thoroughly check the drawing and test the design before using. AS-ASTRO ACCEPTS NO RESPONSIBILITY OR LIABILITY FOR THE PERFORMANCE OF GOODS ON PRODUCTS PRODUCED THEREFROM. ASTRO MAKES NO WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE WITH REGARD TO EXTRUSIONS/PRODUCTS PRODUCED PURSUANT TO THIS DRAWING. ASTRO'S ONLY WARRANTY SHALL BE AS STATED ON ASTRO'S SALES ACKNOWLEDGMENT FORM.





AS - 08075 STANDARD COMMERCIAL TOLERANCES FOR EXTRUDED BAR AS REF. NO. AND SHAPES APPLY UNLESS SPECIFICALLY SHOWN OTHERWISE

ASTRO DIE NO.

2.617



5.003



- (*) INDICATES 0.017 R (4)
- (*) INDICATES 0.020 R (8)
- (*) INDICATES 0.031 R (2)
- (o) INDICATES 0.035 R (6)
- (A) INDICATES 0.050 R (2)
- (o) INDICATES 0.132 R (2)
- ALL UNSPECIFIED WALL THICKNESS TO BE 0.100 IN.
- ALL UNSPECIFIED CORNERS & FILLETS TO BE 0.015 R



EST. AREA	1.619	SQ. IN.	EST. WT./FT.	1.943	LBS.	HOLLOW CLASS
EST. OS. PER.	19.831	IN.	EST. T.O. PER.	33.720	IN.	65 MAIN STREET
CIRCLE DIA.	5.37	IN.	FACTOR	17	APP. NO.	110
REV. A) CHANGE PRIMARY ALLOY	-		6005 WAS	6063		DESCRIPTION 5" GLAZING BAR
REV. B) INDICATES 0.017 R (4)	-					CUSTOMER FOUR SEASONS SOLAR STATE NY
REV. C) INDICATES 0.020 R (8)	-					CUST. PART NO. 5LB5
REV. D) INDICATES 0.031 R (2)	-					DATE 10/24/96
REV. E) INDICATES 0.035 R (6)	-					
REV. F) INDICATES 0.050 R (2)	-					
REV. G) INDICATES 0.132 R (2)	-					
REV. H) ALL UNSPECIFIED WALL THICKNESS TO BE 0.100 IN.	-					
REV. I) ALL UNSPECIFIED CORNERS & FILLETS TO BE 0.015 R	-					
REV. J) PRIMARY ALLOY & TEMPER : 6005-15	-					
REV. K) 07/14/97 N.K.M.	-					

EST. AREA	1.619	SQ. IN.	EST. WT./FT.	1.943	LBS.	HOLLOW CLASS
EST. OS. PER.	19.831	IN.	EST. T.O. PER.	33.720	IN.	65 MAIN STREET
CIRCLE DIA.	5.37	IN.	FACTOR	17	APP. NO.	110
REV. A) CHANGE PRIMARY ALLOY	-		6005 WAS	6063		DESCRIPTION 5" GLAZING BAR
REV. B) INDICATES 0.017 R (4)	-					CUSTOMER FOUR SEASONS SOLAR STATE NY
REV. C) INDICATES 0.020 R (8)	-					CUST. PART NO. 5LB5
REV. D) INDICATES 0.031 R (2)	-					DATE 10/24/96
REV. E) INDICATES 0.035 R (6)	-					
REV. F) INDICATES 0.050 R (2)	-					
REV. G) INDICATES 0.132 R (2)	-					
REV. H) ALL UNSPECIFIED WALL THICKNESS TO BE 0.100 IN.	-					
REV. I) ALL UNSPECIFIED CORNERS & FILLETS TO BE 0.015 R	-					
REV. J) PRIMARY ALLOY & TEMPER : 6005-15	-					
REV. K) 07/14/97 N.K.M.	-					

ETC Laboratories Report #: ETC-08-1014-21317
 Verified By: MHS

AS - 05638 / 03300 This is not an ASME drawing. It is the responsibility of the customer to determine if the performance of parts or products produced therefrom meet the requirements of the applicable standard or specification. No warranty of merchantability or fitness for a particular purpose with regard to extrusions/products produced pursuant to this drawing. Astro's only warranty shall be as stated on Astro's Sales Acknowledgment form.

Report #: AS-05638
 Date: 04/10/2009
 AS REF. NO. AND SHAPES APPLY UNLESS SPECIFICALLY SHOWN OTHERWISE
 AS REF. NO. AND SHAPES APPLY UNLESS SPECIFICALLY SHOWN OTHERWISE
 ASTRO DIE NO. : 6627 A
 ASTRO DIE NO.



ASTRO SHAPES, INC.					
65 MAIN STREET STRUTHERS, OHIO 44471					
DESCRIPTION	MUNTIN	APP. NO.	SCALE	DRAWN	KMM
A) REVISE QTY OF V-GROOVES - QTY (4) WAS QTY (14)			3=1		
2-PLACES AS SHOWN					
CUSTOMER FOUR SEASONS SOLAR STATE NY					
REVISIONS					
ALL UNSPECIFIED CORNERS & FILLETS TO BE 0.015 R					
ALL UNSPECIFIED WALL THICKNESS TO BE A/S IN.					
PRIMARY ALLOY & TEMPER : 6063-T5					
4MTB					
B/B/95 N.K.M.					
CUST. PART NO.					

TMIE BLOCK TB0002 02/24/98 Revision 0 Approval Number 56215-601
 (1) INDICATES 0.022 R (10)
 (2) INDICATES 0.023 R (2)
 (3) INDICATES 0.040 R (2)
 ALL UNSPECIFIED CORNERS & FILLETS TO BE 0.015 R

TMIE BLOCK TB0002 02/24/98 Revision 0 Approval Number 56215-601
 (1) INDICATES 0.022 R (10)
 (2) INDICATES 0.023 R (2)
 (3) INDICATES 0.040 R (2)
 ALL UNSPECIFIED CORNERS & FILLETS TO BE 0.015 R

ASTRO DIE NO. : 6627 A


ETC Laboratories Report #: ETC-08-1014-2131
Verified By: J. M. S. Date: 04/10/2009

This is not an Astro design. It is Astro's interpretation of the section designed and supplied by its Customer. Customer should thoroughly check the drawing and test the design before using. ASTRO ACCEPTS NO RESPONSIBILITY OR LIABILITY FOR THE PERFORMANCE OF GOODS OR PRODUCTS PURCHASED THEREFROM. ASTRO MAKES NO WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE WITH REGARD TO EXTRUSIONS/PRODUCTS PRODUCED PURSUANT TO THIS DRAWING. ASTRO'S ONLY WARRANTY SHALL BE AS STATED ON ASTRO'S SALES ACKNOWLEDGMENT FORM.

AS-0664 STANDARD COMMERCIAL TOLERANCES FOR EXTRUDED BAR AND SHAPES APPLY UNLESS SPECIFICALLY SHOWN OTHERWISE AS REF. NO. 6625 ASTRO DIE NO.

11

ASTRO DIE NO. : 6625



EXPOSED

REVISIONS				DESCRIPTION				DRAWN BY		DATE	
EST. AREA	SQ IN.	EST. W./FT.	LBS.	SOLID CLASS	ASTRO SHAPES, INC.			NAME	NUMBER	STATE	NY
O.S. PER.	IN.	EST. TOT. PER.	IN.	110	66 MAIN STREET STRUTHERS, OHIO 44471						
CIRCLE DATA	0.043	2.050	0.051	APP. NO.				SCALE 2=1	DRAWN	KHM	DATE 01/07/95
									CUSTOMER	FOUR SEASONS SOLAR	
											4BC
									CUST. PART NO.		

(*) INDICATES 0.005 R. (2)

ALL UNSPECIFIED CORNERS & FILLETS TO BE 1/8 IN. R.
ALL UNSPECIFIED WALL THICKNESS TO BE 1/2 IN.



ETC Laboratories Report #: ETC-08-1014-2-317
 Verified By: MG Date: 04/10/2009

AS-0512
 AS-0512
 AS-0512


This is not an ASME drawing. It is the manufacturer's interpretation of the design. Customer shall be responsible for the design and tooling before work. AS-0512 ACCEPTS NO RESPONSIBILITY OR LIABILITY FOR THE PERFORMANCE OF GOODS OR PRODUCTS PRODUCED THEREON. AS-0512 MAKES NO WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO EXTRUSION PRODUCTS PRODUCED PURSUANT TO THIS DRAWING. ASTRO'S ONLY WARRANTY SHALL BE AS STATED ON ASTRO'S SALES CONTRACTS.

AS-0512 STANDARD COMMERCIAL TOLERANCES FOR EXTRUDED BAR AS REF. NO. AND SHAPES APPLY UNLESS SPECIFICALLY SHOWN OTHERWISE
 ASTRO DIE NO.

NOTE - THDS. OFFSET FOR



ASTRO ID - 0.010 DP.
 X 90°



LEN	0.194	SQIN	EFF YEL	0.232	US	SOLID	ASTRO SHAPES, INC.
LEN	6.929	IN.	PER. 6.929	IN.	CLASS	66 MAIN STREET	STRUTHERS, OHIO 44471
CROSS PER.	10	PER. 6.929	IN.	110	APP. NO.		
CIRCLE	2.25	IN.	FACTOR 30				
DIA.							
(B)	REVERSE QTY OF Y-GROOVES - QTY (4) WAS QTY (16)						
2-PLACES AS SHOWN							
REVISIONS	2-1						
	BROWN KHM						
	SCALE 08/25/94						
	CUSTOMER FOUR SEASONS SOLAR						
	STATE NY						
	8/8/95 N.K.M.						
	CUST. PART NO.						
	4MMB						

(1) INDICATES 0.022 R (4)
 (2) INDICATES 0.028 R (2)
 (3) INDICATES 0.060 R (2)
 ALL UNSPECIFIED WALL THICKNESS TO BE 0.056 IN.
 ALL UNSPECIFIED CORNERS & FILLETS TO BE 0.015 R
 PRIMARY ALLOY & TEMPER : 6063-T5
 DATE 08/25/94
 APPROVED BY: MG
 FILE NUMBER: 08/25/94
 PRODNO: 08/25/94

LEN	0.194	SQIN	EFF YEL	0.232	US	SOLID	ASTRO SHAPES, INC.
LEN	6.929	IN.	PER. 6.929	IN.	CLASS	66 MAIN STREET	STRUTHERS, OHIO 44471
CROSS PER.	10	PER. 6.929	IN.	110	APP. NO.		
CIRCLE	2.25	IN.	FACTOR 30				
DIA.							
(B)	REVERSE QTY OF Y-GROOVES - QTY (4) WAS QTY (16)						
2-PLACES AS SHOWN							
REVISIONS	2-1						
	BROWN KHM						
	SCALE 08/25/94						
	CUSTOMER FOUR SEASONS SOLAR						
	STATE NY						
	8/8/95 N.K.M.						
	CUST. PART NO.						
	4MMB						